



ILLINOIS ENVIRONMENTAL PROTECTION AGENCY

1021 NORTH GRAND AVENUE EAST, P.O. BOX 19276, SPRINGFIELD, ILLINOIS 62794-9276 • (217)782-3397

JB PRITZKER, GOVERNOR

JOHN J. KIM, DIRECTOR

MEMORANDUM

DATE: September 8, 2021

TO: Maureen Wozniak, Kent Mohr,
Eric Jones and Ron Robeen

FROM: Yasmine Keppner-Bauman, Compliance Unit

RE: Proposed Compliance Commitment Agreement from
Koppers Inc
Violation Notice A-2021-00217
I.D. 031300AAJ

Please find attached a proposed Compliance Commitment Agreement (CCA) received from the facility in response to the above-referenced Violation Notice dated July 15, 2021. This facility is requesting a meeting.

Rockford • 4302 N. Main St., Rockford, IL 61103 • (815) 987-7760

Elgin • 595 S. State, Elgin, IL 60123 • (847) 608-3131

Champaign • 2125 S. First St., Champaign, IL 61820 • (217) 278-5800

Collinsville • 1101 Eastport Plaza Dr, Suite 100, Collinsville, IL 62234 • (618) 346-5120

Des Plaines • 9511 Harrison St., Des Plaines, IL 60016 • (847) 294-4000

Peoria • 412 SW Washington St, Suite D., Peoria, IL 61602 • (309) 671-3022

Marion • 2309 W. Main St., Suite 116, Marion, IL 62959 • (618) 993-7200



September 3, 2021

Via E-mail and Certified U.S. Mail

Yasmine Keppner-Bauman
Illinois Environmental Protection Agency
Bureau of Air/Filed Operations Section
1021 North Grand Ave. East
P.O. Box 19276
Springfield, IL 62794-9276
Yasmine.Keppner-Bauman@Illinois.gov

Koppers Inc.
Carbon Materials and Chemicals
3900 South Laramie Avenue
Cicero, IL 60804-4523
Tel 708 222 3483
Fax 708 656 6079
www.koppers.com

**Re: Violation Notice A-2021-00217
ID: 031300AAJ**

Dear Ms. Keppner-Bauman:

Koppers Inc. ("Koppers") appreciates this opportunity to provide the Illinois Environmental Protection Agency ("IEPA") with its initial response to Violation Notice A-2021-00217, which was received by Koppers on July 21, 2021. It is Koppers' intention to cooperatively participate in the Section 31 enforcement process and, if determined to be necessary, to provide IEPA with a proposed Compliance Commitment Agreement following the meeting with IEPA requested herein. Koppers willingness to participate in the Section 31 enforcement process is not, and should not be, construed as an admission of liability and Koppers expressly reserves its rights and any defenses with respect to the alleged violations.

Initial Response to Alleged Violations

As a threshold matter, Koppers respectfully disagrees with IEPA's assertions that the December 26, 2020 and March 20, 2021 fires resulted in violations of the statutory, regulatory and permit provisions cited by the Violation Notice.

The cited statutory, regulatory and permit provisions are intended to address process emissions from regulated sources and emission units and were never intended to apply to accidental fire events. The emissions from accidental fire events are not process emissions *from* regulated sources or emission units and, consequently, are not violations of the cited provisions. Emissions resulting from an accidental fire *at* an emission unit are not the same as regulated process emissions *from* that emission unit. For example, if someone constructs a house and it burns to the ground due to an accidental fire, emissions from that fire are not process emissions from a regulated source or

RECEIVED
STATE OF ILLINOIS
SEP 07 2021
ENVIRONMENTAL PROTECTION AGENCY
BUREAU OF AIR

the same vein, if Koppers had simply constructed Tube Heater #2 pursuant to construction permit 11100041 but never operated it, and, years later, Tube Heater #2 subsequently burned to the ground due to an accidental fire, would that event result in violations of Sections 9(a) and 9(b) of the Act, or permit condition 2(a)? Koppers respectfully submits that the answer is “no”. It is Koppers position, therefore, that the existence of a permitted, operating source does not mean that emissions resulting from an accidental fire at the source are regulated process emissions from the source.

Additionally, with respect to the alleged violations of 35 Ill. Adm. Code 212.123(a) and related permit provisions, the regulations explain how violations of those provisions are determined. *See* 35 Ill. Adm. Code 212.125 (“Violations of Sections 212.122 and 212.123 of this Subpart shall be determined ...”). By the plain language of the regulation, there is no violation of Section 212.123, or related permit provisions, unless determined by the methods set forth in Section 212.125. That did not occur here.

Koppers, below, and preserving the foregoing arguments, responds to each of the alleged violations as set forth in Attachment A to the Violation Notice.

Response to Specific Alleged Violations

1. Sections 9(a) and 9(b) of the Act, 35 Ill. Adm. Code 212.123(a), and condition 2(a) of construction permit 11100041: Koppers, Inc. caused or allowed smoke or other PM from Tube Heater #2 for Tar Distillation System #2, with an opacity greater than 30 percent as the result of a fire on December 26, 2020.

Koppers’ Response: Koppers, for the reasons above, disputes this violation.

Copies of Koppers January 22, 2021 deviation report and subsequent March 10, 2021 letter to IEPA regarding the December 26, 2020 fire event are attached hereto as Attachments 1 and 2. As explained in that correspondence, the Stickney facility’s Tar Plant Tubeheaters are process heaters where heat exchange occurs between combustion gases and material contained in tubes in the exhaust flow of the combustion gases. Under normal operation, the only emission from the Tar Plant Tubeheaters is the combustion exhaust. The Tubeheaters are capable of firing natural gas or process gas. At the time of the fire, Tubeheater #2 was natural gas-fired only.

A root-cause analysis for the December 26, 2020 fire concluded that the fire started due to a combination of events that included equipment failure and procedural error. During a normal shutdown, material is left circulating and the tubeheater is fired periodically to keep the material warm and flowing. Prior to the incident on Saturday, December 26, 2020, the tubeheater failed to light due to frozen steam piping. A problem occurred with the control valve on unit 1 at approximately the same time. These concurrent equipment failures led directly to the course of events that finally resulted in a tube rupture and fire inside Tubeheater #2.

In the case of an accidental fire, there is not necessarily an act, or actor, that causes, threatens or allows the discharge or emission of contaminants, as required by Section 9(a) of the Act.

The operator informed the Shift Supervisor of the failure of both tubeheaters appropriately and the Shift Supervisor called out electricians to perform troubleshooting and repairs. However, he failed to note the problems in his shift report or turnover during shift relief. As a result, there was no immediate visibility to the day shift staff to ensure proper follow up.

Due to an apparent miscommunication, the electricians only worked on Tubeheater #1, while Tubeheater #2 did not get repaired. Subsequent operators did not further report the problem with Tubeheater #2 because they thought that management was already aware. As a result, the material in the system continued to grow colder over the holiday until it would no longer pump.

With material set up in the piping, startup could not commence until the material was either removed or circulating again. There are safeties in the tubeheater control logic to prevent the tubeheater from starting without adequate circulation. These safeties are in place to prevent overheating of material from causing excess pressure resulting in tube rupture. Due to the hazards associated with bypassing those safeties, procedure requires a supervisor to consult with the plant superintendent so that proper precautions and procedures can be put in place.

When the Area Supervisor began troubleshooting the loss of flow, he found that the material was too cold to pump. Without consulting the superintendent, he bypassed the safeties and began to apply heat. He left the heat running too long and pressure in the tubeheater coil increased until it ruptured and leaked, causing the fire.

The fire resulted in smoke (not process emissions) from the stack exhaust point of Tubeheater #2. This smoke was vented to the atmosphere through Tubeheater #2 stack; however, these were uncontrolled fire emissions from combustion of feedstock and not the normal controlled combustion emissions from fuel combustion. In response, the operators activated the firefighting system that injected steam to the Tubeheater to extinguish the fire. In addition, the operators contacted the fire department immediately and the firefighting crew arrived within 5 minutes. The fire and smoke diminished to completely out over a period of less than 2 hours. The fire department's report was included with Koppers' March 10, 2021 letter. *See Attachment 2, Fire Department Response Report.*

Koppers, as noted in its March 10, 2021 letter, took several corrective actions following December 26, 2020 fire event. Those corrective action included:

- Replacement of the failed components that led to the tubeheaters failing to light;
- Corrective action with the supervisors related to poor communication and failure to follow procedure; and
- Implementation of a new procedure to require repeated notification of shift supervisors of tubeheater trouble at least once per shift and emptying the system if the temperature drops below the prescribed limit. *See Attachment 2, Stickney Plant Work Instruction, Secure Unit When Tubeheater Will Not Light (Cold Circulation), March 8, 2021.*

The Violation Notice requests information regarding emissions of each criteria pollutant from the December 26, 2020 fire event. As explained in Koppers' March 10, 2021 letter, estimating the emissions from the fire (versus controlled combustion of fuel emissions) is challenging and such

an estimate would not result in a realistic emission rate from the event. The permitted emission rates are, as IEPA is aware, established for the facility's fuel combustion exhaust flow and not for an accidental fire event. The information to attempt calculation of emission estimates from the fire does not exist. This information includes the amount and composition of the material combusted, the degree of combustion between partial and complete, the amount of combustion air entering through the dampers at the bottom of the heater, and the temperature of the flame.

With the foregoing caveats and limitations, Koppers has attempted to estimate emissions from the December 26, 2020 fire event. The emissions below are based on AP-42 Chapter 1.3 emission factors for fuel oil and process inputs (sulfur content and raw material combusted). A combustion efficiency penalty was also used to account for incomplete combustion for CO and HAP emissions.

Emissions from Fire Event December 26, 2020		
Amount Combusted	0.6	1000 gallons
Sulfur Content	0.8	%
Efficiency Penalty	50	% for CO and HAPs

Pollutant	Emission Factor (lb/1000 gal)	Emissions (lb)
SO2	157 x %S	0.8
NOx	20	12
CO	5	4.5
PM (total)	3.3	1.98
Benzene	2.14E-04	0.0002
Ethylbenzene	6.36E-05	0.00006
Formaldehyde	3.30E-02	0.03
Naphthalene	1.13E-03	0.0010
Toluene	6.20E-03	0.006
o-Xylene	1.09E-04	0.00010

Notes:

Criteria Pollutant Emission Factors AP42, Table 1.3-1

Hazardous Air Pollutant Emission Factors AP42, Table 1.3-9

Assumption: It is conservatively assumed that all of the tar in the coil drained into the firebox and burned

Finally, Koppers, as noted in its prior correspondence regarding this event, elected to report the event as an exceedance of the 30% opacity limit in Permit No. 11100041, Section 2.a. Koppers, for the reasons above, does not believe this limit was exceeded, but reported the event as indicated out of an abundance of caution.

2. Section 9(b) of the Act and condition 4(c) of construction permit 11100041: Koppers, Inc. failed to operate and maintain Tar Distillation System #2 with Tube Heater #2 in accordance with written procedures to provide good air pollution control practices to minimize emissions.

Koppers' Response: Koppers, for the reasons above, disputes this violation and incorporates herein its response to alleged Violation No. 1.

3. Sections 9(a) and 39.5(6)(a) of the Act, 35 Ill. Adm. Code 212.123(a) and condition 5.2.2(b) of Clean Air Act Permit Program (CAAPP) permit 96030134: Koppers, Inc. caused or allowed smoke or other PM from Tar Distillation System #2, with an opacity greater than 30 percent as the result of a fire on March 20, 2021.

Koppers' Response: Koppers, for the reasons above, disputes this violation.

Koppers notified IEPA of the March 20, 2021 fire by phone and, subsequently, submitted a written report to IEPA on April 16, 2021. A copy of Koppers April 16, 2021 report is attached to this letter as Attachment 3.

As explained in Koppers' prior reporting, on March 20, 2021, there was a fire at the Tar Distillation Column and adjacent scaffolding at approximately 10:20 pm. Upon discovery of the fire, the distillation plant was immediately shut down. Within a few minutes of shutting the process down, the main fire was extinguished. It is Koppers' understanding that the cause of the fire was material which had leaked from the top of Unit 2 distillation column and ignited. Preliminary identification of the leaked material was fuel oil, pyrolysis (CAS No. 69013-21-4), and clarified oils (petroleum), catalytic cracked (CAS No. 64741-624).

Due to damage from the fire it was impossible to determine the exact location of the leak and the ignition source, but a root-cause analysis provided to the Chemical Safety and Hazard Investigation Board details possible contributing causes and corrective actions (this analysis is being provided to you via separate e-mail link, per below). Based on the location of accumulated material and spray pattern on nearby equipment and scaffolding it is most likely that the leak occurred at a flange at the top of the dehydrator section of the distillation unit. A fraction of the leaked material evaporated and the vapors were subsequently ignited by an uncertain ignition source. The most fundamental corrective actions from the incident are focused on minimizing the risk of leaks and eliminating possible ignition sources from the area.

The Violation Notice requests that Koppers estimate emissions from the March 20, 2021 fire event. With the caveats and limitations explained above in response to alleged violation No. 1, Koppers has attempted to estimate emissions from the March 20, 2021, fire event.

Emissions from Fire Event March 20, 2021

Amount Combusted	3	1000 gallons
Sulfur Content	0.8	%
Efficiency Penalty	50	% for CO and HAPs

Pollutant	Emission Factor (lb/1000 gal)	Emissions (lb)
SO2	157 x %S	3.8
NOx	20	60
CO	5	22.5
PM (total)	3.3	9.9
Benzene	2.14E-04	0.0010
Ethylbenzene	6.36E-05	0.00029
Formaldehyde	3.30E-02	0.15
Naphthalene	1.13E-03	0.0051
Toluene	6.20E-03	0.028
o-Xylene	1.09E-04	0.00049

Notes:

Criteria Pollutant Emission Factors AP42, Table 1.3-1

Hazardous Air Pollutant Emission Factors AP42, Table 1.3-9

Assumption: It is conservatively assumed that all of the tar fed to the unit for an hour leaked out and burned

In addition, necessary safety precautions were taken at the onset of the fire to ensure that the Tar Distillation Column was not pressurized. This was accomplished by continuing to run the vacuum system, shutting down the tube heater, and switching to ventilating the vacuum system through the No. 2 Fume Scrubber. For safety reasons, this was continued from 10:20 PM on March 20, 2021 until 8:30 AM on March 21, 2021. The total VOM emissions during this period of 10 hours is estimated at 65.4 lb. There was no combustion of this material, therefore, there are no emissions of other criteria pollutants due to combustion.

4. Section 39.5(6)(a) of the Act and condition 7.4.5(b) of CAAPP permit 96030134: Koppers, Inc. failed to follow good operating practices for the Tar Distillation System #2 and Tube Heater #2 resulting in fires with associated excess opacity on December 26, 2020, and March 20, 2021.

Koppers' Response: Koppers, for the reasons above, disputes this violation and incorporates herein its response to alleged Violation Nos. 1, 2 and 3.

Response to Recommendations

The Violation Notice requests certain inspection, maintenance and repair records be provided in connection with Koppers' response. The requested materials are included with this initial response as Attachment 4. The requested emissions calculations are set forth in the tables above.

In addition to the materials attached to this initial response, Koppers is sending you two separate e-mails with links where you can download: (1) the Chemical Safety and Hazard Investigation Board root-cause analysis materials, which contain photographs and videos of the March 20, 2021 fire event; and (2) post-fire repair records. Please let us know if you do not receive the e-mails or have any difficulty accessing the files via the links provided.

Request for Meeting

Koppers believes it would be useful to meet with representatives of IEPA to discuss the alleged violations, Koppers response to those alleged violations, and the actions IEPA believes are required to address the alleged violations. Following the requested meeting, Koppers will, if necessary, supplement this initial response and submit to IEPA proposed terms for a Compliance Commitment Agreement.

Please contact me at (708) 556-9984, or by e-mail HerringLS@koppers.com, to schedule the requested meeting.

Thank you for considering this initial response to the Violation Notice and request for a meeting. We look forward to meeting with IEPA to address these matters.

Sincerely,


Seth Herring
Plant Manager

Attachments:

- Attachment 1 – Koppers’ January 22, 2021 Deviation Report
 - Attachment 2 – Koppers’ March 10, 2021 Letter to IEPA w/attachments
 - Attachment 3 – Koppers’ April 16, 2021 Letter to IEPA w/attachments
 - Attachment 4 – Requested Inspection, Maintenance and Repair Records
-

ATTACHMENT 1

cc: Mohr
98340



Koppers Inc.
Carbon Materials and Chemicals
3900 South Laramie Avenue
Cicero, IL 60804-4523
Tel 708 222 3483
Fax 708 656 6079
www.koppers.com

January 22, 2021

Illinois Environmental Protection Agency
Bureau of Air
Compliance Section (MC 40)
PO Box 19276
Springfield, IL 62794-9276

RECEIVED
STATE OF ILLINOIS

JAN 26 2021

ENVIRONMENTAL PROTECTION AGENCY
BUREAU OF AIR

RE: Deviation Report
Koppers Inc., Stickney Plant
ID Number: 031300AAJ

To Whom It May Concern:

Koppers Inc. (Koppers) operates a chemical manufacturing plant in Stickney, Illinois under Clean Air Act Permit Program (CAAPP) Permit # 96030134. Condition 5.7 of the CAAPP permit requires Koppers to provide prompt notice to the Illinois Environmental Protection Agency (IEPA) of deviations from CAAPP permit requirements.

The reports are to describe the event, the probable cause of the deviations, any corrective actions or preventive measures taken, and steps to avoid future deviations. The attached Table 1 summarizes a deviation from a requirement of the CAAPP permit.

If there are any questions concerning this report, please contact Ms. Charvi Payghode of Koppers at (708) 566-3103.

Sincerely,

L. Seth Herring
Plant Manager CMC NA

Table 1 – Deviation Summary

Date and Description	On 12/26/2020 there was a fire at the bottom of the #2 tube heater at 10:30am. The Fire Department was called immediately. The quencher was turned on, and Koppers started hosing down the area until the Fire Department arrived. They were able to put out the fire by 11:30am. The PM emissions from this fire likely exceeded the 30% opacity requirement in Permit No. 11100041 condition 2.a.
Cause for Deviation	There was a fire at the #2 tube heater. The root cause is under investigation.
Corrective Action Taken	The quencher was turned on, and Koppers started hosing down the area until the Fire Department arrived. The facility followed the MON SSM Plan to minimize emissions.
Steps Taken to Avoid Future Deviation	The facility is investigating the root cause of the fire and will implement strategies if possible to prevent similar malfunctions from happening in the future.

ATTACHMENT 2

March 10, 2021

Yasmine Keppner-Bauman
Illinois Environmental Protection Agency
Bureau of Air/Filed Operations Section
1021 North Grand Ave. East
P.O. Box 19276
Springfield, IL 62702

**Re: Additional Information on Fire at Tubeheater #2
Koppers Inc.
ID: 031300AAJ**

Dear Ms. Keppner-Bauman:

Koppers Inc. ("Koppers") thanks the Illinois Environmental Protection Agency ("IEPA") for virtually meeting on February 25, 2021 to discuss the fire that occurred in Tubeheater #2 at Koppers' Stickney facility on December 26, 2020. The fire event was reported to IEPA by letter on January 21, 2021. This letter contains additional information regarding the event, as requested by IEPA during the February 25th meeting.

Additional Information Regarding the December 26, 2020 Tube Heater Fire

The Stickney facility's Tar Plant Tubeheaters are process heaters where heat exchange occurs between combustion gases and material contained in tubes in the exhaust flow of the combustion gases. Under normal operation, the only emissions from the Tar Plant Tubeheaters are the combustion exhaust. The Tubeheaters are capable of firing natural gas or process gas. At the time of the fire, Tubeheater #2 was natural gas-fired only.

The root-cause analysis concluded that the fire started due to a combination of events that included equipment failure and procedural error. During a normal shutdown, material is left circulating and the tubeheater is fired periodically to keep the material warm and flowing. Prior to the incident on Saturday, December 26, 2020, the tubeheater failed to light due to frozen steam piping. A problem occurred with the control valve on unit 1 at approximately the same time. These concurrent equipment failures led directly to the course of events that finally resulted in a tube rupture and fire inside Tubeheater #2.

The operator informed the Shift Supervisor of the failure of both tubeheaters appropriately and the Shift Supervisor called out electricians to perform troubleshooting and repairs. However, he failed to note the problems in his shift report or turnover during shift relief. As a result, there was no immediate visibility to the day shift staff to ensure proper follow up.

Due to an apparent miscommunication, the electricians only worked on Tubeheater #1 and Tubeheater #2 did not get repaired. Subsequent operators did not further report the problem with Tubeheater #2 because they thought that management was already aware. As a result, the material in the system continued to grow colder over the holiday until it would no longer pump.

With material set up in the piping, startup could not commence until the material was either removed or circulating again. There are safeties in the tubeheater control logic to prevent the tubeheater from starting without adequate circulation. These safeties are in place to prevent overheating of material from causing excess pressure resulting in tube rupture. Due to the hazards associated with bypassing those safeties, procedure requires a supervisor to consult with the plant superintendent so that proper precautions and procedures can be put in place.

When the Area Supervisor began troubleshooting the loss of flow, he found that the material was too cold to pump. Without consulting the superintendent, he bypassed the safeties and began to apply heat. He left the heat running too long and pressure in the tubeheater coil increased until it ruptured and leaked causing the fire.

The fire resulted in smoke (not process emissions) from the stack exhaust point of Tubeheater #2. This smoke was vented to the atmosphere through Tubeheater #2 stack; however, these were uncontrolled fire emissions from combustion of feedstock and not the normal controlled combustion emissions from fuel combustion. In response, the operators activated the firefighting system that injected steam to the Tubeheater to extinguish the fire. In addition, the operators contacted the fire department immediately and the firefighting crew arrived within 5 minutes. The fire and smoke diminished to completely out over a period of less than 2 hours. A copy of the fire department's report is attached to this letter.

Corrective actions following this incident include:

- Replacement of the failed components that led to the tubeheaters failing to light
- Corrective action with the supervisors related to poor communication and failure to follow procedure, and
- Implementation of a new procedure to require repeated notification of shift supervisors of tubeheater trouble at least once per shift and emptying the system if the temperature drops below the prescribed limit.

Estimating the emissions from the fire (versus controlled combustion of fuel emissions) is challenging and such an estimate would not result in a realistic emission rate from the event. The permitted emission rates are, as IEPA is aware, established for the facility's fuel combustion

exhaust flow and not for an accidental fire event. The information to attempt calculation of emission estimates from the fire does not exist. This information includes the amount and composition of the material combusted, the degree of combustion between partial and complete, the amount combustion air entering through the dampers at the bottom of the heater, and the temperature of the flame. Koppers elected to report the event as an exceedance of the 30% opacity limit in Permit No. 11100041, Section 2.a.

Thank you for considering this additional information to the report of the fire event at Tube Heater #2. Please contact me, or Charvi Payghode, Environmental Manager (708-222-4688, Payghodeck@koppers.com), if you would like to discuss this information or require any additional information.

Sincerely,



L. Seth Herring
Plant Manager
Carbon Materials and Chemicals

Attachments:

- 1 – Secure Unit when Tubeheater will not light (Cold Circulation) Procedure
- 2 – Fire Department Response Report

Attachment 1

Secure Unit when Tubeheater will not light (Cold Circulation) Procedure

Document No.: WI-TAR-0058
Subject: Secure unit when tubeheater
will not light

Written by: B. Michalowski
Approved by: S. Herring

Koppers Inc.
Effective Date: 3/8/2021
Revision Number: 0
Page 1 of 2

Secure Unit When Tubeheater Will Not Light (Cold Circulation)

Purpose:

To provide the method for securing the unit when the tubeheater will not light and material becomes too cold to maintain reliable circulation.

Safety, Health and Environmental Considerations

PPE requirements:

Standard PPE - Class B (ANSI Z89.1) hard hat, Safety glasses w/side shields (ANZI Z87), Metatarsal safety boots (minimum six-inch lace type), Long sleeved shirt/pant (cotton work uniform). Personal H2S monitor (cricket)

Physical Hazards: None

Chemical Hazards: H2S exposure

Environmental Considerations: None

Other requirements: None

Accountability

All production employees are responsible for knowing this procedure.

Relevant Documents

WI-TAR-0023 Tar Distillation Unit Shutdown

Procedure

Any time you cannot light the tubeheater to maintain the temperature of the reboiler loop while circulating follow these steps:

1. Notify Supervisor. This must be done at least once per shift to ensure that the current shift supervisor is aware of the issue.
 - a. Shift supervisor is to call out for an electrician or other craftsman to address the problem.
2. If the Bottom of Column temperature drops below 125C inform the supervisor that the situation is becoming critical.
 - a. Supervisor is to immediately inform the electrical supervisor and tar superintendent that the tubeheater will not light.
3. If the Bottom of Column temperature drops below 110C the operator is to inform the supervisor and execute a complete shut down as detailed in the Unit Shutdown Work Instruction (WI-TAR-0023)

**Stickney Plant
Work Instruction**



Document No.: WI-TAR-0058
Subject: Secure unit when tubeheater
will not light

Written by: B. Michalowski
Approved by: S. Herring

Koppers Inc.
Effective Date: 3/8/2021
Revision Number: 0
Page 2 of 2

Revision History

Revision Number	Prepared by	Date	Summary of Changes
0	B. Michalowski	3/8/2021	Initial issue

Attachment 2

Fire Department Response Report

A CS852 IL 12 26 2020 1ST 20-0001175 000 Delete Change No Activity **MFIRS -1 Basic**

B Location* Check this box to indicate that the address for this incident is provided on the Wildland Fire Module in Section 2 "Alternative Location Specification". Use only for Wildland fires. Census Tract 8207

Street address 3900 S Laramie AVE
 Number/Milepost Prefix Street or Highway Street Type Suffix

Intersection
 In front of
 Rear of
 Adjacent to
 Directions

Stickney IL 60402
 Apt./Suite/Room City State Zip Code

Cross street or directions, as applicable

C Incident Type * 162 Outside equipment fire
 Incident Type

D Aid Given or Received*
 1 Mutual aid received
 2 Automatic aid recvd. Their FDID Their State
 3 Mutual aid given
 4 Automatic aid given
 5 Other aid given
 N None Their Incident Number

E1 Date & Times Midnight is 0000
 Check boxes if dates are the same as Alarm ALARM always required
 Date. Alarm * 12 26 2020 10:17:00
 ARRIVAL required, unless canceled or did not arrive
 Arrival * 12 26 2020 10:21:00
 CONTROLLED Optional, except for wildland fires
 Controlled
 LAST UNIT CLEARED, required except for wildland fires
 Last Unit Cleared 12 26 2020 11:56:00

E2 Shift & Alarms
 Local Option
1 IND
 Shift or Alarms District Platoon

E3 Special Studies
 Local Option
 Special Study ID# Special Study Value

F Actions Taken *
11 Extinguishment by fire
 Primary Action Taken (1)
 Additional Action Taken (2)
 Additional Action Taken (3)

G1 Resources *
 Check this box and skip this section if an Apparatus or Personnel form is used.
 Apparatus Personnel
 Suppression 0004 0009
 EMS
 Other
 Check box if resource counts include aid received resources.

G2 Estimated Dollar Losses & Values
 LOSSES: Required for all fires if known. Optional for non fires. None
 Property \$ 000 000
 Contents \$ 000 000
 PRE-INCIDENT VALUE: Optional
 Property \$ 000 000
 Contents \$ 000 000

Completed Modules
 Fire-2
 Structure-3
 Civil Fire Cas.-4
 Fire Serv. Cas.-5
 EMS-6
 HazMat-7
 Wildland Fire-8
 Apparatus-9
 Personnel-10
 Arson-11

H1* Casualties None
 Deaths Injuries
 Fire Service 0 0
 Civilian 0 0

H2 Detector
 Required for Confined Fires.
 1 Detector alerted occupants
 2 Detector did not alert them
 U Unknown

H3 Hazardous Materials Release
 N None
 1 Natural Gas: slow leak, no evacuation or HazMat actions
 2 Propane gas: < 15 lb. tank (as in home BBQ grill)
 3 Gasoline: vehicle fuel tank or portable container
 4 Kerosene: fuel burning equipment or portable storage
 5 Diesel fuel/fuel oil: vehicle fuel tank or portable
 6 Household solvents: home/office small, cleanup only
 7 Motor oil: from engine or portable container
 8 Paint: from paint can containing < 5 gallons
 0 Other: Special HazMat actions required or spill > 55 gal., Please complete the HazMat Form

I Mixed Use Property
 NN Not Mixed
 10 Assembly use
 20 Education use
 33 Medical use
 40 Residential use
 51 Row of stores
 53 Enclosed mall
 58 Bus. & Residential
 59 Office use
 60 Industrial use
 63 Military use
 65 Farm use
 00 Other mixed use

J Property Use* Structures
 131 Church, place of worship
 161 Restaurant or cafeteria
 162 Bar/Tavern or nightclub
 213 Elementary school or kindergarten
 215 High school or junior high
 241 College, adult education
 311 Care facility for the aged
 331 Hospital

Outside
 124 Playground or park
 655 Crops or orchard
 669 Forest (timberland)
 807 Outdoor storage area
 919 Dump or sanitary landfill
 931 Open land or field

341 Clinic, clinic type infirmary
 342 Doctor/dentist office
 361 Prison or jail, not juvenile
 419 1-or 2-family dwelling
 429 Multi-family dwelling
 439 Rooming/boarded house
 449 Commercial hotel or motel
 459 Residential, board and care
 464 Dormitory/barracks
 519 Food and beverage sales

539 Household goods, sales, repairs
 579 Motor vehicle/boat sales/repair
 571 Gas or service station
 599 Business office
 615 Electric generating plant
 629 Laboratory/science lab
 700 Manufacturing plant
 819 Livestock/poultry storage (barn)
 882 Non-residential parking garage
 891 Warehouse

936 Vacant lot
 938 Graded/care for plot of land
 946 Lake, river, stream
 951 Railroad right of way
 960 Other street
 961 Highway/divided highway
 962 Residential street/driveway

981 Construction site
 984 Industrial plant yard

Lookup and enter a Property Use code only if you have NOT checked a Property Use box:
 Property Use 700
Manufacturing, processing
 MFIRS-1 Revision 03/11/99

K1 Person/Entity Involved Local Option **KOPPERS INDUSTRIES** Business name (if applicable) Area Code **630** Phone Number **605** **4380**

Check This Box if same address as incident location. Then skip the three duplicate address lines.

Tom Mr., Ms., Mrs. First Name MI **Tortoriello** Last Name Suffix

3900 Number **S** Prefix **Laramie** Street or Highway **AVE** Street Type Suffix

Post Office Box Apt./Suite/Room **Stickney** City

IL State **60402** Zip Code

More people involved? Check this box and attach Supplemental Forms (MIFRS-18) as necessary

K2 Owner Local Option Same as person involved? Then check this box and skip the rest of this section. Business name (if Applicable) Area Code Phone Number

Check this box if same address as incident location. Then skip the three duplicate address lines.

Mr., Ms., Mrs. First Name MI Last Name Suffix

Number Prefix Street or Highway Street Type Suffix

Post Office Box Apt./Suite/Room City

State Zip Code

I Remarks Local Option **12/26/2020 13:31:45 Jacob Anderson**

Crew called for the report of fire at Koppers Chemicals. Upon arrival crew found a large header of smoke coming from one of the stacks on property. Engine 1203 gave report and assumed Koppers command. Crew made contact with facility staff, who were already flowing a hydrant mounted deluge gun onto fire. Staff stated it was ok to flow water on product. 1203 stretched a 2 1/2 inch preconnect to the south of the stack that was on fire and obtained a positive water supply. Crew noted a heavy fire presence from the bottom of the stack. The stack in question was Tar 2 Tube Heater 2, staff stated the supply of product was shut off along with gas. Chief 1210 arrived on scene and assumed command. FVFD engine 812 was instructed to take position to the west of stack and hit the upper parts of stack with deck gun. Crews were sure to stay out of smoke and uphill/upwind. Koppers provided SDS paperwork on product. SDS ID 00228334. Air quality was noted with zeros across the board. Fire was extinguished and staff stated they would continue with their in house fire mitigation for the time being. Crews cleaned up and were released by command with no further issues.

I Authorization

15309 Officer in charge ID	Anderson, Jacob P Signature	CP Position or rank	 Assignment	12 Month	26 Day	2020 Year
Check Box if same as Officer Member making report ID in charge. <input checked="" type="checkbox"/> 15309	Anderson, Jacob P Signature	CP Position or rank	 Assignment	12 Month	26 Day	2020 Year

CS852

FDID *

IL

State *

MM

DD

YYYY

12

26

2020

Incident Date *

1ST

Station

20-0001175

Incident Number *

000

Exposure *

Complete
Narrative

Narrative:

12/26/2020 13:31:45 Jacob Anderson

Crew called for the report of fire at Koppers Chemicals. Upon arrival crew found a large header of smoke coming from one of the stacks on property. Engine 1203 gave report and assumed Koppers command. Crew made contact with facility staff, who were already flowing a hydrant mounted deluge gun onto fire. Staff stated it was ok to flow water on product. 1203 stretched a 2 1/2 inch preconnect to the south of the stack that was on fire and obtained a positive water supply. Crew noted a heavy fire presence from the bottom of the stack. The stack in question was Tar 2 Tube Heater 2, staff stated the supply of product was shut off along with gas. Chief 1210 arrived on scene and assumed command. FVFD engine 812 was instructed to take position to the west of stack and hit the upper parts of stack with deck gun. Crews were sure to stay out of smoke and uphill/upwind. Koppers provided SDS paperwork on product. SDS ID 00228334. Air quality was noted with zeros across the board. Fire was extinguished and staff stated they would continue with their in house fire mitigation for the time being. Crews cleaned up and were released by command with no further issues.

A CS852 IL 12 26 2020 1ST 20-0001175 000 Delete Change No Activity **NFIRS -2**
 FDID * State * Incident Date * Station Incident Number * Exposure * **Fire**

B Property Details

B1 Residential **Not Residential**
 Estimated Number of residential living units in building of origin whether or not all units became involved

B2 Buildings involved **Buildings not involved**
 Number of buildings involved

B3 Acres burned (outside fires) **None** **Less than one acre**

C On-Site Materials or Products None **Complete if there were any significant amounts of commercial, industrial, energy or agricultural products or materials on the Property, whether or not they became involved**

Enter up to three codes. Check one or more boxes for each code entered.

611 Industrial
 On-site material (1)

 On-site material (2)

 On-site material (3)

1 Bulk storage or warehousing
 2 Processing or manufacturing
 3 Packaged goods for sale
 4 Repair or service

1 Bulk storage or warehousing
 2 Processing or manufacturing
 3 Packaged goods for sale
 4 Repair or service

1 Bulk storage or warehousing
 2 Processing or manufacturing
 3 Packaged goods for sale
 4 Repair or service

D Ignition

D1 64 Incinerator area
 Area of fire origin *

D2 UU Undetermined
 Heat source *

D3 UU Undetermined
 Item first ignited * 1 Check Box if fire spread was confined to object of origin

D4
 Type of material first ignited Required only if item first ignited code is 00 or <70

E1 Cause of Ignition

Check box if this is an exposure report. Skip to section G

1 Intentional
 2 Unintentional
 3 Failure of equipment or heat source
 4 Act of nature
 5 Cause under investigation
 U Cause undetermined after investigation

E2 Factors Contributing To Ignition None

20 Mechanical
 Factor Contributing To Ignition (1)

 Factor Contributing To Ignition (2)

E3 Human Factors Contributing To Ignition

Check all applicable boxes

1 Asleep **None**
 2 Possibly impaired by alcohol or drugs
 3 Unattended person
 4 Possibly mental disabled
 5 Physically Disabled
 6 Multiple persons involved

7 Age was a factor
 Estimated age of person involved

1 Male 2 Female

F1 Equipment Involved In Ignition

None If Equipment was not involved, Skip to Section G

 Equipment Involved

Brand

Model

Serial #

Year

F2 Equipment Power

 Equipment Power Source

F3 Equipment Portability

1 Portable
 2 Stationary

Portable equipment normally can be moved by one person, is designed to be use in multiple locations, and requires no tools to install.

G Fire Suppression Factors

Enter up to three codes. **None**

NNN None
 Fire suppression factor (1)

 Fire suppression factor (2)

 Fire suppression factor (3)

H1 Mobile Property Involved

None

1 Not involved in ignition, but burned
 2 Involved in ignition, but did not burn
 3 Involved in ignition and burned

 Mobile property model

 License Plate Number State VIN Number

H2 Mobile Property Type & Make

 Mobile property type

 Mobile property make

 Year

Local Use

Pre-Fire Plan Available
 Some of the information presented in this report may be based upon reports from other Agencies

Arson report attached
 Police report attached
 Coroner report attached
 Other reports attached

NFIRS-2 Revision 01/19/99

A CS852 IL 12 26 2020 1ST 20-0001175 000 Delete Change **MFIRS - 9 Apparatus or Resources**
FDID * State * Incident Date * Station Incident Number * Exposure *

B Apparatus or * Resource	Date and Times					Sent <input checked="" type="checkbox"/>	Number of * People	Use <small>Check ONE box for each apparatus to indicate its main use at the incident.</small>	Actions Taken	
	<small>Check if same as alarm date</small>									
	Month	Day	Year	Hour	Min			<input type="checkbox"/> Suppression	<input type="checkbox"/> EMS	<input type="checkbox"/> Other
1 ID <u>1203</u> Type <u>11</u>	<input checked="" type="checkbox"/>	<u>12</u>	<u>26</u>	<u>2020</u>	<u>10:17</u>	<input checked="" type="checkbox"/>	<u>4</u>	<input checked="" type="checkbox"/> Suppression <input type="checkbox"/> EMS <input type="checkbox"/> Other	<input type="checkbox"/>	<input type="checkbox"/>
2 ID <u>1208</u> Type <u>60</u>	<input checked="" type="checkbox"/>	<u>12</u>	<u>26</u>	<u>2020</u>	<u>10:17</u>	<input checked="" type="checkbox"/>	<u>1</u>	<input checked="" type="checkbox"/> Suppression <input type="checkbox"/> EMS <input type="checkbox"/> Other	<input type="checkbox"/>	<input type="checkbox"/>
3 ID <u>1210</u> Type <u>92</u>	<input checked="" type="checkbox"/>	<u>12</u>	<u>26</u>	<u>2020</u>	<u>10:17</u>	<input checked="" type="checkbox"/>	<u>1</u>	<input checked="" type="checkbox"/> Suppression <input type="checkbox"/> EMS <input type="checkbox"/> Other	<input type="checkbox"/>	<input type="checkbox"/>
4 ID <u>STANBY</u> Type <u>NN</u>	<input checked="" type="checkbox"/>	<u>12</u>	<u>26</u>	<u>2020</u>	<u>10:17</u>	<input checked="" type="checkbox"/>	<u>3</u>	<input checked="" type="checkbox"/> Suppression <input type="checkbox"/> EMS <input type="checkbox"/> Other	<input type="checkbox"/>	<input type="checkbox"/>
5 ID <u> </u> Type <u> </u>	<input type="checkbox"/>	<u> </u>	<u> </u>	<u> </u>	<u> </u>	<input type="checkbox"/>	<u> </u>	<input type="checkbox"/> Suppression <input type="checkbox"/> EMS <input type="checkbox"/> Other	<input type="checkbox"/>	<input type="checkbox"/>
6 ID <u> </u> Type <u> </u>	<input type="checkbox"/>	<u> </u>	<u> </u>	<u> </u>	<u> </u>	<input type="checkbox"/>	<u> </u>	<input type="checkbox"/> Suppression <input type="checkbox"/> EMS <input type="checkbox"/> Other	<input type="checkbox"/>	<input type="checkbox"/>
7 ID <u> </u> Type <u> </u>	<input type="checkbox"/>	<u> </u>	<u> </u>	<u> </u>	<u> </u>	<input type="checkbox"/>	<u> </u>	<input type="checkbox"/> Suppression <input type="checkbox"/> EMS <input type="checkbox"/> Other	<input type="checkbox"/>	<input type="checkbox"/>
8 ID <u> </u> Type <u> </u>	<input type="checkbox"/>	<u> </u>	<u> </u>	<u> </u>	<u> </u>	<input type="checkbox"/>	<u> </u>	<input type="checkbox"/> Suppression <input type="checkbox"/> EMS <input type="checkbox"/> Other	<input type="checkbox"/>	<input type="checkbox"/>
9 ID <u> </u> Type <u> </u>	<input type="checkbox"/>	<u> </u>	<u> </u>	<u> </u>	<u> </u>	<input type="checkbox"/>	<u> </u>	<input type="checkbox"/> Suppression <input type="checkbox"/> EMS <input type="checkbox"/> Other	<input type="checkbox"/>	<input type="checkbox"/>

Type of Apparatus or Resources

<p>Ground Fire Suppression</p> <ul style="list-style-type: none"> 11 Engine 12 Truck or aerial 13 Quint 14 Tanker & pumper combination 16 Brush truck 17 AAF (Aircraft Rescue and Firefighting) 10 Ground fire suppression, other <p>Heavy Ground Equipment</p> <ul style="list-style-type: none"> 21 Dozer or plow 22 Tractor 24 Tanker or tender 20 Heavy equipment, other <p>Aircraft</p> <ul style="list-style-type: none"> 41 Aircraft: fixed wing tanker 42 Helitanker 43 Helicopter 40 Aircraft, other 	<p>Marine Equipment</p> <ul style="list-style-type: none"> 51 Fire boat with pump 52 Boat, no pump 50 Marine apparatus, other <p>Support Equipment</p> <ul style="list-style-type: none"> 61 Breathing apparatus support 62 Light and air unit 60 Support apparatus, other <p>Medical & Rescue</p> <ul style="list-style-type: none"> 71 Rescue unit 72 Urban Search & rescue unit 73 High angle rescue unit 75 BLS unit 76 ALS unit 70 Medical and rescue unit, other 	<div style="border: 1px solid black; padding: 5px; width: fit-content;"> <p>More Apparatus? Use Additional Sheets</p> </div> <p>Other</p> <ul style="list-style-type: none"> 91 Mobile command post 92 Chief officer car 93 HazMat unit 94 Type 1 hand crew 95 Type 2 hand crew 99 Privately owned vehicle 00 Other apparatus/resource <p> <small> NN None UU Undetermined </small> </p>
-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

MFIRS-9 Revision 11/17/98

A FDID * CS852 State * IL Incident Date * MM 12 DD 26 YYYY 2020 Station 18T Incident Number * 20-0001175 Exposure * 000 Delete Change **MFIRS - 10 Personnel**

B Apparatus or Resource * Use codes listed below

Date and Times Check if same as alarm date
Month Day Year Hours/mins

Sent X

Number of People * 4

Use Check ONE box for each apparatus to indicate its main use at the incident.
 Suppression
 EMS
 Other

Actions Taken List up to 4 actions for each apparatus and each personnel.

1 ID 1203 Dispatch 12 26 2020 10:17 Sent X
Arrival 12 26 2020 10:21 4
Type 11 Clear 12 26 2020 11:56 Suppression
 EMS
 Other

Personnel ID	Name	Rank or Grade	Attend <input checked="" type="checkbox"/> X	Action Taken	Action Taken	Action Taken	Action Taken
15309	Anderson, Jacob	CP	X				
15310	Kozubowski, Craig	PF	X				
15311	Maldonado, Franklin	PF	X				
15380	Iovino, Dominick	FF	X				

2 ID 1208 Dispatch 12 26 2020 10:17 Sent X
Arrival 12 26 2020 10:30 1
Type 60 Clear 12 26 2020 11:56 Suppression
 EMS
 Other

Personnel ID	Name	Rank or Grade	Attend <input checked="" type="checkbox"/> X	Action Taken	Action Taken	Action Taken	Action Taken
15302	Babinec, John	DC	X				

3 ID 1210 Dispatch 12 26 2020 10:17 Sent X
Arrival 12 26 2020 10:21 1
Type 92 Clear 12 26 2020 11:56 Suppression
 EMS
 Other

Personnel ID	Name	Rank or Grade	Attend <input checked="" type="checkbox"/> X	Action Taken	Action Taken	Action Taken	Action Taken
15314	Boyajian, Jeff	FC	X				

A FDID * CS852 State * IL Incident Date * MM 12 DD 26 YYYY 2020 Station 1ST Incident Number * 20-0001175 Exposure * 000 Delete Change **MFIRS - 10 Personnel**

B Apparatus or Resource * Use codes listed below

Date and Times Check if same as alarm date
 Month Day Year Hours/mins

Dispatch 12 26 2020 10:17 Sent 3 Use Suppression EMS Other

Arrival 12 26 2020 10:21 Sent 3 Use Suppression EMS Other

Clear 12 26 2020 11:56 Sent 3 Use Suppression EMS Other

Actions Taken: List up to 4 actions for each apparatus and each personnel.

Personnel ID	Name	Rank or Grade	Attend <input checked="" type="checkbox"/>	Action Taken	Action Taken	Action Taken	Action Taken
15335	Rousseau, Josh		X				
15372	Corsini, Mark	FF	X				
15374	Abboud, Nicholas	FF	X				

2 ID Dispatch Sent Use Suppression EMS Other

Type Arrival Sent Use Suppression EMS Other

Clear Sent Use Suppression EMS Other

Personnel ID	Name	Rank or Grade	Attend <input checked="" type="checkbox"/>	Action Taken	Action Taken	Action Taken	Action Taken
			<input type="checkbox"/>				
			<input type="checkbox"/>				
			<input type="checkbox"/>				
			<input type="checkbox"/>				
			<input type="checkbox"/>				
			<input type="checkbox"/>				

3 ID Dispatch Sent Use Suppression EMS Other

Type Arrival Sent Use Suppression EMS Other

Clear Sent Use Suppression EMS Other

Personnel ID	Name	Rank or Grade	Attend <input checked="" type="checkbox"/>	Action Taken	Action Taken	Action Taken	Action Taken
			<input type="checkbox"/>				
			<input type="checkbox"/>				
			<input type="checkbox"/>				
			<input type="checkbox"/>				
			<input type="checkbox"/>				
			<input type="checkbox"/>				

CS852 FDID *	IL State *	MM DD YYYY 12 26 2020 Incident Date *	1ST Station	20-0001175 Incident Number *	000 Exposure *	Responding Personnel
-----------------	---------------	---------------------------------------------	----------------	---------------------------------	-------------------	-------------------------

Staff ID\Staff Name	Unit	Activity	Position	Rank	PayScl	Hrs	HrsPd	Pts
15309 Anderson, Jacob P	1203	FIRECALL Fire call OF		CP		1.65	1.65	0.00
15310 Kozubowski, Craig	1203	FIRECALL Fire call R1		PF		1.65	1.65	0.00
15311 Maldonado, Franklin	1203	FIRECALL Fire call R2		PF		1.65	1.65	0.00
15380 Iovino, Dominick	1203	X FIRECALL Fire call DR		FF		1.65	1.65	0.00
15302 Babinec, John C	1208	X FIRECALL Fire call DR		DC		1.65	1.65	0.00
15314 Boyajian, Jeff G	1210	X FIRECALL Fire call CM		FC		1.65	1.65	0.00
15335 Rousseau, Josh	STANBY	FIRECALL Fire call ST				1.65	1.65	0.00
15372 Corsini, Mark	STANBY	FIRECALL Fire call ST		FF		1.65	1.65	0.00
15374 Abboud, Nicholas	STANBY	FIRECALL Fire call ST		FF		1.65	1.65	0.00

Total Participants: 9

Total Personnel Hours: 14.85

An 'X' next to the unit denotes driver.

CS852 FDID	IL State	12 26 Incident Date	2020	1ST Station	20-0001175 Incident Number	000 Exposure	Responding Units/Personnel
---------------	-------------	--------------------------	------	----------------	-------------------------------	-----------------	-------------------------------

Unit	Notify Time	Enroute Time	Arrival Time	Cleared Time
1203 Crimson Fire engine	10:17:00	10:18:00	10:21:00	11:56:00

Staff ID\Staff Name	Activity	Rank	Position	Role
15309 Anderson, Jacob P	Fire call	Captain	Officer's se	Captain
15310 Kozubowski, Craig	Fire call	Probationar	Rear seat #1	
15311 Maldonado, Franklin	Fire call	Probationar	Rear seat #2	
15380 Iovino, Dominick	Fire call	Firefighter	Driver	Driver of th

1208 Apparatus/Staff, Utility car	10:17:00	10:25:00	10:30:00	11:56:00
-----------------------------------	----------	----------	----------	----------

Staff ID\Staff Name	Activity	Rank	Position	Role
15302 Babinec, John C	Fire call	Deputy Chie	Driver	Deputy Chief

1210 Fire Chief	10:17:00	10:18:00	10:21:00	11:56:00
-----------------	----------	----------	----------	----------

Staff ID\Staff Name	Activity	Rank	Position	Role
15314 Boyajian, Jeff G	Fire call	Fire Chief	Command	Chief

STANBY Standing by in quarters	10:17:00	10:18:00	10:21:00	11:56:00
--------------------------------	----------	----------	----------	----------

Staff ID\Staff Name	Activity	Rank	Position	Role
15335 Rousseau, Josh	Fire call		Station	
15372 Corsini, Mark	Fire call	Firefighter	Station	
15374 Abboud, Nicholas	Fire call	Firefighter	Station	

A MM DD, YYYY
 CS852 IL 12 26 2020 1ST 20-0001175 000 Delete MFIRS - 18
 RUID State Incident Date Station Incident Number Exposure Change Supplemental

K1 Person/Entity Involved KOPPERS INDUSTRIES Phone Number

Check this box if same address as incident location. Then skip the three duplicate address lines.

Mr.,Ms., Mrs. First Name MI Last Name Suffix
Gregg Bambuhle

Number Prefix Street or highway Street Type Suffix
3900 S Laramie AVE

Post office box Apt./Suite/Room City
 Stickney

State Zip Code
IL 60402

K2 Person/Entity Involved Business name if applicable Phone Number

Check this box if same address as incident location. Then skip the three duplicate address lines.

Mr.,Ms., Mrs. First Name MI Last Name Suffix

Number Prefix Street or highway Street Type Suffix

Post office box Apt./Suite/Room City

State Zip Code

K3 Person/Entity Involved Business name if applicable Phone Number

Check this box if same address as incident location. Then skip the three duplicate address lines.

Mr.,Ms., Mrs. First Name MI Last Name Suffix

Number Prefix Street or highway Street Type Suffix

Post office box Apt./Suite/Room City

State Zip Code

K4 Person/Entity Involved Business name if applicable Phone Number

Check this box if same address as incident location. Then skip the three duplicate address lines.

Mr.,Ms., Mrs. First Name MI Last Name Suffix

Number Prefix Street or highway Street Type Suffix

Post office box Apt./Suite/Room City

State Zip Code

K5 Person/Entity Involved Business name if applicable Phone Number

Check this box if same address as incident location. Then skip the three duplicate address lines.

Mr.,Ms., Mrs. First Name MI Last Name Suffix

Number Prefix Street or highway Street Type Suffix

Post office box Apt./Suite/Room City

State Zip Code

MFIRS-11 Revision 6/9/98

C8852	IL	12	26	2020	18T	20-0001175	000	MPIRS - Involvement User Fields
<small>IDID</small>	<small>State</small>	<small>MM</small>	<small>DD</small>	<small>YYYY</small>	<small>Station</small>	<small>Incident Number</small>	<small>Exposure</small>	

Involvement

Name:

Tortoriello, Tom

Involvement

Type:

Owner:

Occupant:

Involvement

Name:

Bambuhle, Gregg

Involvement

Type:

Owner:

Occupant:

ATTACHMENT 3

KOPPERS

Koppers Carbon Materials & Chemicals
3900 South Laramie
Cicero, Illinois, 60804
Tel 708 656 5900
www.koppers.com

Ms. Yasmine Keppner-Bauman
Illinois Environmental Protection Agency
Bureau of Air
Compliance Section (MC 40)
PO Box 19276
Springfield, IL 62794-9276

RE: Follow-up Communications on Tar Distillation Fire
Koppers Inc., Stickney Plant
ID Number: 031300AAJ

Dear Ms. Keppner-Bauman:

Koppers Inc. (Koppers) operates a chemical manufacturing plant in Stickney, Illinois under Clean Air Act Permit Program (CAAPP) Permit # 96030134. On March 20, 2021, there was a fire at the Tar Distillation Column and adjacent scaffolding at approximately 10:20 pm. In an effort to keep the Illinois Environmental Protection Agency informed on matters that may lead to inquiries from concerned citizens in the area of the plant, Koppers reported the incident to the IEPA via telephone. This letter is sent as a follow-up report regarding that incident.

Upon discovery of the fire, the distillation plant was immediately shut down. Within a few minutes of shutting the process down, the main fire was extinguished. It is Koppers' understanding that the cause of the fire was material which had leaked from the top of Unit 2 distillation column and ignited. Preliminary identification of the leaked material is fuel oil, pyrolysis (CAS No. 69013-21-4), and clarified oils (petroleum), catalytic cracked (CAS No. 64741-624). The root cause is still under further investigation as the equipment is dismantled. Attached to this letter is the fire department response to the incident.

The facility continues to investigate the root cause of the fire and will implement strategies, as appropriate, to prevent similar incidents from happening in the future.

Condition 5.7 of the CAAPP permit requires Koppers to provide prompt notice to the Illinois Environmental Protection Agency of deviations from CAAPP permit requirements. Here, because the incident was a fire on the outside of the distillation column, no stack vented emissions occurred and there was no deviation from permit limits. Due to the relatively short duration of the fire and the time of day in which it occurred, Koppers does not believe that there were significant effects to the surrounding community.

If there are any questions concerning this report, please contact Ms. Charvi Payghode of Koppers at (708) 222-4688.

Sincerely,

A handwritten signature in black ink, appearing to read "L. Seth Herring". The signature is written in a cursive style with a long horizontal stroke at the end.

L. Seth Herring
Plant Manager CMC NA

Attachment

Stickney Fire Department Report

A		MM DD YYYY 03 20 2021	1ST Station	21-0000243 Incident Number	000 Exposure	<input type="checkbox"/> Delete <input type="checkbox"/> Change <input type="checkbox"/> No Activity	NFIRS -1 Basic
B Location*		<input type="checkbox"/> Check this box to indicate that the address for this incident is provided on the Wildland Fire Module in Section 8 "Alternative Location Specification". Use only for Wildland fires.					
<input checked="" type="checkbox"/> Street address <input type="checkbox"/> Intersection <input type="checkbox"/> In front of <input type="checkbox"/> Rear of <input type="checkbox"/> Adjacent to <input type="checkbox"/> Directions		3900 S Laramie <small>Number/Milepost Prefix Street or Highway</small>		AVE <small>Street Type Suffix</small>		8207 <small>Contra Tract</small>	
		Stickney <small>Apt./Suite/Room City</small>		IL 60402 <small>State Zip Code</small>			
C Incident Type *		E1 Date & Times		E2 Shift & Alarms			
111 Building fire <small>Incident Type</small>		Midnight is 0000 Check boxes if dates are the same as Alarm Date. Alarm * 03 20 2021 22:31:00 <small>Month Day Year Hr Min Sec</small> ARRIVAL required, unless canceled or did not arrive		Local Option 3 IND <small>Shift or Alarms District Platoon</small>			
D Aid Given or Received*		<input checked="" type="checkbox"/> Arrival * 03 20 2021 22:34:00 <small>CONTROLLED Optional, except for wildland fires</small>		E3 Special Studies Local Option Special Study ID# Special Study Value			
1 <input type="checkbox"/> Mutual aid received 2 <input checked="" type="checkbox"/> Automatic aid recv. 3 <input type="checkbox"/> Mutual aid given 4 <input type="checkbox"/> Automatic aid given 5 <input type="checkbox"/> Other aid given N <input type="checkbox"/> None		<input type="checkbox"/> Controlled <small>LAST UNIT CLEARED, required except for wildland fires</small> Last Unit <input type="checkbox"/> Cleared 03 21 2021 01:44:00					
F Actions Taken *		G1 Resources *		G2 Estimated Dollar Losses & Values			
11 Extinguishment by fire <small>Primary Action Taken (1)</small> Additional Action Taken (2) Additional Action Taken (3)		<input checked="" type="checkbox"/> Check this box and skip this section if an Apparatus or Personnel form is used. Apparatus Personnel Suppression 0003 0006 EMS Other <input type="checkbox"/> Check box if resource counts include aid received resources.		LOSSES: Required for all fires if known. Optional for non fires. Property \$ 000 000 <input checked="" type="checkbox"/> Contents \$ 000 000 <input checked="" type="checkbox"/> FIRE-INCIDENT VALUE: Optional Property \$ 000 000 <input type="checkbox"/> Contents \$ 000 000 <input type="checkbox"/>			
Completed Modules		H1* Casualties		H3 Hazardous Materials Release		I Mixed Use Property	
<input checked="" type="checkbox"/> Fire-2 <input checked="" type="checkbox"/> Structure-3 <input type="checkbox"/> Civil Fire Cas.-4 <input type="checkbox"/> Fire Serv. Cas.-5 <input type="checkbox"/> EMS-6 <input type="checkbox"/> HazMat-7 <input type="checkbox"/> Wildland Fire-8 <input checked="" type="checkbox"/> Apparatus-9 <input checked="" type="checkbox"/> Personnel-10 <input type="checkbox"/> Arson-11		None Deaths Injuries Fire Service Civilian H2 Detector Required for Confined Fires. 1 <input type="checkbox"/> Detector alerted occupants 2 <input checked="" type="checkbox"/> Detector did not alert them U <input type="checkbox"/> Unknown		None 1 <input type="checkbox"/> Natural Gas: slow leak, no evacuation or Ruckit actions 2 <input type="checkbox"/> Propane gas: <1 lb. tank (as in home BBQ grill) 3 <input type="checkbox"/> Gasoline: vehicle fuel tank or portable container 4 <input type="checkbox"/> Kerosene: fuel burning equipment or portable storage 5 <input type="checkbox"/> Diesel fuel/fuel oil: vehicle fuel tank or portable 6 <input type="checkbox"/> Household solvents: home/office spill, cleanup only 7 <input type="checkbox"/> Motor oil: lawn engine or portable container 8 <input type="checkbox"/> Paint: even paint cans totaling < 55 gallons 0 <input type="checkbox"/> Other: Special Ruckit actions required or spill > 55 gal., Please complete the Ruckit form.		NN <input type="checkbox"/> Not Mixed 10 <input type="checkbox"/> Assembly use 20 <input type="checkbox"/> Education use 33 <input type="checkbox"/> Medical use 40 <input type="checkbox"/> Residential use 51 <input type="checkbox"/> Row of stores 53 <input type="checkbox"/> Enclosed mall 58 <input type="checkbox"/> Bus. & Residential 59 <input type="checkbox"/> Office use 60 <input checked="" type="checkbox"/> Industrial use 63 <input type="checkbox"/> Military use 65 <input type="checkbox"/> Farm use 00 <input type="checkbox"/> Other mixed use	
J Property Use*		Structures		Outside			
131 <input type="checkbox"/> Church, place of worship 161 <input type="checkbox"/> Restaurant or cafeteria 162 <input type="checkbox"/> Bar/Tavern or nightclub 213 <input type="checkbox"/> Elementary school or kindergarten 215 <input type="checkbox"/> High school or junior high 241 <input type="checkbox"/> College, adult education 311 <input type="checkbox"/> Care facility for the aged 331 <input type="checkbox"/> Hospital		341 <input type="checkbox"/> Clinic, clinic type infirmary 342 <input type="checkbox"/> Doctor/dentist office 361 <input type="checkbox"/> Prison or jail, not juvenile 419 <input type="checkbox"/> 1-or 2-family dwelling 429 <input type="checkbox"/> Multi-family dwelling 439 <input type="checkbox"/> Rooming/boarded house 449 <input type="checkbox"/> Commercial hotel or motel 459 <input type="checkbox"/> Residential, board and care 464 <input type="checkbox"/> Dormitory/barracks 519 <input type="checkbox"/> Food and beverage sales		936 <input type="checkbox"/> Vacant lot 938 <input type="checkbox"/> Graded/care for plot of land 946 <input type="checkbox"/> Lake, river, stream 951 <input type="checkbox"/> Railroad right of way 960 <input type="checkbox"/> Other street 961 <input type="checkbox"/> Highway/divided highway 962 <input type="checkbox"/> Residential street/driveway			
		539 <input type="checkbox"/> Household goods, sales, repairs 579 <input type="checkbox"/> Motor vehicle/boat sales/repair 571 <input type="checkbox"/> Gas or service station 599 <input type="checkbox"/> Business office 615 <input type="checkbox"/> Electric generating plant 629 <input type="checkbox"/> Laboratory/science lab 700 <input checked="" type="checkbox"/> Manufacturing plant 819 <input type="checkbox"/> Livestock/poultry storage (barn) 882 <input type="checkbox"/> Non-residential parking garage 891 <input type="checkbox"/> Warehouse		981 <input type="checkbox"/> Construction site 984 <input type="checkbox"/> Industrial plant yard Lookup and enter a Property Use code only if you have NOT checked a Property Use box: Property Use 700 Manufacturing, processing			

K1 Person/Entity Involved

Local Option

KOPPERS INDUSTRIES

Business name (if applicable)

630

Area Code

605

Phone Number

4380

 Check this box if same address as incident location. Then skip the three duplicate address lines.

 Tom
Mr., Ms., Mrs. First Name

 Tortoriello
MI Last Name

Suffix

 3900
Number Prefix Street or Highway

 AVE
Street Type Suffix

Post Office Box Apt./Suite/Room City

 IL 60402
State Zip Code

 More people involved? Check this box and attach Supplemental Forms (SFIRS-18) as necessary
K2 Owner

Local Option

 Same as person involved? Then check this box and skip the rest of this section.

Business name (if applicable)

Area Code

Phone Number

 Check this box if same address as incident location. Then skip the three duplicate address lines.

Mr., Ms., Mrs. First Name

MI Last Name

Suffix

Number Prefix Street or Highway

Street Type Suffix

Post Office Box Apt./Suite/Room City

State Zip Code
L Remarks

Local Option

03/21/2021 11:59:09 Jacob Anderson

Crew called for the report of a fire. Upon arrival crew found a large tar plant facility with a fire contained to the tar distillery building (approximately 100 x 50). Crew noted the fire to be on the third floor A/B corner with extension to the stacks above the building. Koppers staff were on scene attempting to extinguish with hydrant mounted monitors and advised the material was tar and water could be used on it. Engine 1201 took position in the A/B corner to hit the fire with deck gun and made a positive water supply. Central Stickney Truck 906 took position in the B/C corner and raised aerial to hit what was burning on the stacks. McCook engine positioned in C/D corner of building to hit hot spots with deck gun. Crews made good progress and extinguished what was burning. Staff were on scene throughout duration of event. They believed the material was extinguished but still wanted crews to remain on scene for awhile longer. Crews noted some steam pipes were damaged during the fire and koppers would work to isolate these. Scene was turned over to Koppers staff with no further issues.

03/22/2021 16:29:33 Jeffrey Boyajian

Dispatched to location for reported structure fire. Upon going enroute I was given an update by PD on the scene that the fire was confirmed. Upon gathering this information as well as the amount of fire seen upon arrival, I upgraded the response to the full still level. Upon reaching the Tar Distillation building, we had heavy fire noted on the North/East face of the building, as well as extension to the South face and North face of the building which extended up the piping and to the top portions of the structure. Upon doing a 360 degree survey of the building I had Engine 1201 take the front of the structure

L Authorization
 15314
Officer in charge ID

 Boyajian, Jeff G
Signature

 FC
Position or rank

Assignment

 03 21 2021
Month Day Year

 Check Box if same as Officer in charge.

 15309
Number making report ID

 Anderson, Jacob P
Signature

 CP
Position or rank

Assignment

 03 21 2021
Month Day Year

CS852

FDIB

★

IL

State ★

MM DD YYYY

3

20

2021

Incident Data ★

1ST

Station

21-0000243

Incident Number ★

000

Exposure ★

Complete Narrative

Narrative:

03/21/2021 11:59:09 Jacob Anderson

Crew called for the report of a fire. Upon arrival crew found a large tar plant facility with a fire contained to the tar distillery building (approximately 100 x 50). Crew noted the fire to be on the third floor A/B corner with extension to the stacks above the building. Koppers staff were on scene attempting to extinguish with hydrant mounted monitors and advised the material was tar and water could be used on it. Engine 1201 took position in the A/B corner to hit the fire with deck gun and made a positive water supply. Central Stickney Truck 906 took position in the B/C corner and raised aerial to hit what was burning on the stacks. McCook engine positioned in C/D corner of building to hit hot spots with deck gun. Crews made good progress and extinguished what was burning. Staff were on scene throughout duration of event. They believed the material was extinguished but still wanted crews to remain on scene for awhile longer. Crews noted some steam pipes were damaged during the fire and koppers would work to isolate these. Scene was turned over to Koppers staff with no further issues.

03/22/2021 16:29:33 Jeffrey Boyajian

Dispatched to location for reported structure fire. Upon going enroute I was given an update by PD on the scene that the fire was confirmed. Upon gathering this information as well as the amount of fire seen upon arrival, I upgraded the response to the full still level. Upon reaching the Tar Distillation building, we had heavy fire noted on the North/East face of the building, as well as extension to the South face and North face of the building which extended up the piping and to the top portions of the structure. Upon doing a 360 degree survey of the building I had Engine 1201 take the front of the structure where they began to establish a water supply and began extinguishment with the deck gun (master stream). I relocated to the front of the plant and established a Command Post and was speaking with Jaime Duarte who was the plant supervisor that night, I established that no one was injured and everyone accounted for, he confirmed. Engine 1201 reported water pressure issues. I then exited my vehicle and noticed that I did not hear the diesel fire pump running and asked why it was not, no-one knew why it was not. I directed Central Stickney's ladder truck to set up on the East side of the structure and McCooks Engine to set up on the West side of the structure, and went to the pump house to see what the issue was with the pump, while preparing companies in staging to prepare for a water supply if the pump was not functional. After arriving in the pump house the "Operational Panel" was signalling the pump was "ON" but obviously was not running. At that time I turned the switch to the manual position and started the pump manually. Once pump was running our water supply issues were no longer an issue. Once the water supply was established, Central Stickney ladder began flowing water for extinguishment to the upper portions of the structure while being fed by Ciceros engine, 1201 continued with extinguishment of the North face of the structure and McCook's engine was set up on the West side and was assisting with extinguishment with their deck gun (master stream). While the water supply issue was being addressed, Jaime and his crew shut down the product being fed into that building remotely. I released all companies that remained in staging. After conferring with Seth Herring and Gregg Bambule from Koppers they agreed with shutting down extinguishment procedures and waiting to see if the fire was extinguished. After a half hour it was determined that the fire was out and what we were seeing was steam. I had all working companies begin to pick up and released them as soon as they were in service. All companies were released and returning to quarters by 1:30 A.M..

Scene was then turned over to Plant Manager Seth Herring and Koppers personnel.

Narrative:

Command was terminated.

03/23/2021 15:43:32 Jeffrey Boyajian

I received information today regarding times that the incident was reported from our dispatch center (Consolidated Emergency Center of Cook County) .

1st Call was received at 10:24 .29 and caller hung up

Dispatch tried calling back at 10:24.51 and got a recording

2nd Call was received at 10:27.19 and Brandon reported the fire in unit #1

Police Department reported Fire at 10:28.15 via radio to dispatch

A <input type="text" value="CS052"/> <input type="text" value="IL"/> <input type="text" value="03"/> <input type="text" value="20"/> <input type="text" value="2021"/> <input type="text" value="18T"/> <input type="text" value="21-0000243"/> <input type="text" value="000"/>		<input type="checkbox"/> Delete <input type="checkbox"/> Change <input type="checkbox"/> No Activity	NFIRS -2 Fire
B Property Details B1 <input type="text"/> <input checked="" type="checkbox"/> Not Residential Estimated Number of residential living units in building of origin whether or not all units became involved B2 <input type="text"/> <input checked="" type="checkbox"/> Buildings not involved Number of buildings involved B3 <input type="text"/> <input type="checkbox"/> None Acres burned (outside fires) <input type="checkbox"/> Less than one acre		C On-Site Materials or Products <input type="checkbox"/> None Complete if there were any significant amounts of commercial, industrial, energy or agricultural products or materials on the Property, whether or not they became involved Enter up to three codes. Check one or more boxes for each code entered. <input type="text" value="000"/> <input type="text" value="On-site materials,"/> On-site material (1) <input type="text"/> <input type="text"/> On-site material (2) <input type="text"/> <input type="text"/> On-site material (3)	
D Ignition D1 <input type="text" value="UU"/> <input type="text" value="Undetermined"/> Area of fire origin D2 <input type="text" value="UU"/> <input type="text" value="Undetermined"/> Heat source D3 <input type="text" value="UU"/> <input type="text" value="Undetermined"/> Item first ignited <input type="checkbox"/> Check box if fire spread was confined to object of origin D4 <input type="text"/> <input type="text"/> Type of material first ignited Required only if item first ignited code is 00 or <70		E1 Cause of Ignition <input type="checkbox"/> Check box if this is an exposure report. Skip to section G 1 <input type="checkbox"/> Intentional 2 <input type="checkbox"/> Unintentional 3 <input type="checkbox"/> Failure of equipment or heat source 4 <input type="checkbox"/> Act of nature 5 <input checked="" type="checkbox"/> Cause under investigation 6 <input type="checkbox"/> Cause undetermined after investigation	E3 Human Factors Contributing To Ignition Check all applicable boxes 1 <input type="checkbox"/> Asleep <input checked="" type="checkbox"/> None 2 <input type="checkbox"/> Possibly impaired by alcohol or drugs 3 <input type="checkbox"/> Unattended person 4 <input type="checkbox"/> Possibly mental disabled 5 <input type="checkbox"/> Physically Disabled 6 <input type="checkbox"/> Multiple persons involved 7 <input type="checkbox"/> Age was a factor Estimated age of person involved <input type="text"/> 1 <input type="checkbox"/> Male 2 <input type="checkbox"/> Female
F1 Equipment Involved In Ignition <input type="checkbox"/> None if Equipment was not involved, skip to Section G <input type="text"/> <input type="text"/> Equipment Involved Brand <input type="text"/> Model <input type="text"/> Serial # <input type="text"/> Year <input type="text"/>		F2 Equipment Power <input type="text"/> <input type="text"/> Equipment Power Source F3 Equipment Portability 1 <input type="checkbox"/> Portable 2 <input type="checkbox"/> Stationary Portable equipment normally can be moved by one person, is designed to be use in multiple locations, and requires no tools to install.	G Fire Suppression Factors Enter up to three codes. <input checked="" type="checkbox"/> None <input type="text" value="MNN"/> <input type="text" value="None"/> Fire suppression factor (1) <input type="text"/> <input type="text"/> Fire suppression factor (2) <input type="text"/> <input type="text"/> Fire suppression factor (3)
H1 Mobile Property Involved <input type="checkbox"/> None 1 <input type="checkbox"/> Not involved in ignition, but burned 2 <input type="checkbox"/> Involved in ignition, but did not burn 3 <input type="checkbox"/> Involved in ignition and burned <input type="text"/> Mobile property model <input type="text"/> <input type="text"/> License Plate Number State VIN Number		H2 Mobile Property Type & Make <input type="text"/> <input type="text"/> Mobile property type <input type="text"/> <input type="text"/> Mobile property make <input type="text"/> <input type="text"/> Year	
Local Use <input type="checkbox"/> Pre-Fire Plan Available Some of the information presented in this report may be based upon reports from other Agencies <input type="checkbox"/> Arson report attached <input type="checkbox"/> Police report attached <input type="checkbox"/> Coroner report attached <input type="checkbox"/> Other reports attached			

I1 Structure Type * <small>If fire was in enclosed building or a portable/mobile structure complete the rest of this form</small> 1 <input checked="" type="checkbox"/> Enclosed Building 2 <input type="checkbox"/> Portable/mobile structure 3 <input type="checkbox"/> Open structure 4 <input type="checkbox"/> Air supported structure 5 <input type="checkbox"/> Tent 6 <input type="checkbox"/> Open platform (e.g. piers) 7 <input type="checkbox"/> Underground structure (work areas) 8 <input type="checkbox"/> Connective structure (e.g. fences) 9 <input type="checkbox"/> Other type of structure	I2 Building Status * 1 <input type="checkbox"/> Under construction 2 <input checked="" type="checkbox"/> Occupied & operating 3 <input type="checkbox"/> Idle, not routinely used 4 <input type="checkbox"/> Under major renovation 5 <input type="checkbox"/> Vacant and secured 6 <input type="checkbox"/> Vacant and unsecured 7 <input type="checkbox"/> Being demolished 8 <input type="checkbox"/> Other 9 <input type="checkbox"/> Undetermined	I3 Building* Height <small>Count the ROOF as part of the highest story</small> <u>001</u> <small>Total number of stories at or above grade</small> <u> </u> <small>Total number of stories below grade</small>	I4 Main Floor Size* <small>NFIRS-3 Structure Fire</small> <u> </u> , <u>001</u> , <u>000</u> Total square feet OR <u> </u> , <u> </u> BY <u> </u> , <u> </u> Length in feet Width in feet
J1 Fire Origin * <u>001</u> <input type="checkbox"/> Below Grade Story of fire origin	J3 Number of Stories Damaged By Flame <small>Count the ROOF as part of the highest story</small> <u> </u> Number of stories w/ minor damage (1 to 24# flame damage) <u> </u> Number of stories w/ significant damage (25 to 49# flame damage) <u> </u> Number of stories w/ heavy damage (50 to 74# flame damage) <u> </u> Number of stories w/ extreme damage (75 to 100# flame damage)	K Material Contributing Most To Flame Spread <input type="checkbox"/> Check if no flame spread OR same as material first ignited OR unable to determine Skip To Section L K1 <u> </u> <u> </u> Item contributing most to flame spread K2 <u> </u> <u> </u> Type of material contributing most of flame spread Required only if item contributing code is 00 or 70	
J2 Fire Spread * 1 <input type="checkbox"/> Confined to object of origin 2 <input type="checkbox"/> Confined to room of origin 3 <input type="checkbox"/> Confined to floor of origin 4 <input checked="" type="checkbox"/> Confined to building of origin 5 <input type="checkbox"/> Beyond building of origin	L1 Presence of Detectors * <small>(In area of the fire)</small> N <input type="checkbox"/> None Present Skip to section M 1 <input checked="" type="checkbox"/> Present U <input type="checkbox"/> Undetermined	L3 Detector Power Supply 1 <input type="checkbox"/> Battery only 2 <input type="checkbox"/> Hardwire only 3 <input type="checkbox"/> Plug in 4 <input type="checkbox"/> Hardwire with battery 5 <input type="checkbox"/> Plug in with battery 6 <input type="checkbox"/> Mechanical 7 <input type="checkbox"/> Multiple detectors & power supplies 8 <input type="checkbox"/> Other _____ 9 <input checked="" type="checkbox"/> Undetermined	L5 Detector Effectiveness Required if detector operated 1 <input type="checkbox"/> Alerted Occupants, occupants responded 2 <input type="checkbox"/> Occupants failed to respond 3 <input type="checkbox"/> There were no occupants 4 <input type="checkbox"/> Failed to alert occupants 5 <input type="checkbox"/> Undetermined
L2 Detector Type 1 <input type="checkbox"/> Smoke 2 <input type="checkbox"/> Heat 3 <input type="checkbox"/> Combination smoke - heat 4 <input type="checkbox"/> Sprinkler, water flow detection 5 <input checked="" type="checkbox"/> More than 1 type present 6 <input type="checkbox"/> Other _____ 7 <input type="checkbox"/> Undetermined	L4 Detector Operation 1 <input type="checkbox"/> Fire too small to activate 2 <input type="checkbox"/> Operated (Complete Section L5) 3 <input type="checkbox"/> Failed to Operate (Complete Section L6) 4 <input checked="" type="checkbox"/> Undetermined	L6 Detector Failure Reason Required if detector failed to operate 1 <input type="checkbox"/> Power failure, shutoff or disconnect 2 <input type="checkbox"/> Improper installation or placement 3 <input type="checkbox"/> Defective 4 <input type="checkbox"/> Lack of maintenance, includes cleaning 5 <input type="checkbox"/> Battery missing or disconnected 6 <input type="checkbox"/> Battery discharged or dead 7 <input type="checkbox"/> Other _____ 8 <input type="checkbox"/> Undetermined	
M1 Presence of Automatic Extinguishment System * N <input type="checkbox"/> None Present 1 <input checked="" type="checkbox"/> Present Complete rest of Section M	M3 Automatic Extinguishment System Operation Required if fire was within designed range 1 <input type="checkbox"/> Operated & effective (Go to M4) 2 <input type="checkbox"/> Operated & not effective (M4) 3 <input type="checkbox"/> Fire too small to activate 4 <input type="checkbox"/> Failed to operate (Go to M5) 5 <input type="checkbox"/> Other 6 <input type="checkbox"/> Undetermined	M5 Automatic Extinguishment System Failure Reason Required if system failed 1 <input type="checkbox"/> System shut off 2 <input type="checkbox"/> Not enough agent discharged 3 <input type="checkbox"/> Agent discharged but did not reach fire 4 <input type="checkbox"/> Wrong type of system 5 <input type="checkbox"/> Fire not in area protected 6 <input type="checkbox"/> System components damaged 7 <input type="checkbox"/> Lack of maintenance 8 <input type="checkbox"/> Manual Intervention 9 <input type="checkbox"/> Other _____ 10 <input type="checkbox"/> Undetermined	
M2 Type of Automatic Extinguishment System * Required if fire was within designed range of AES 1 <input checked="" type="checkbox"/> Wet pipe sprinkler 2 <input type="checkbox"/> Dry pipe sprinkler 3 <input type="checkbox"/> Other sprinkler system 4 <input type="checkbox"/> Dry chemical system 5 <input type="checkbox"/> Foam system 6 <input type="checkbox"/> Halogen type system 7 <input type="checkbox"/> Carbon dioxide (CO ₂) system 8 <input type="checkbox"/> Other special hazard system 9 <input type="checkbox"/> Undetermined	M4 Number of Sprinkler Heads Operating Required if system operated <u> </u> Number of sprinkler heads operating		

NFIRS-3 Revision 01/19/99

B Apparatus or Resource	Date and Times					Sent <input checked="" type="checkbox"/>	Number of People	Use Check ONE box for each apparatus to indicate its main use at the incident.	Actions Taken	
	Check if same as alarm date									
	Month	Day	Year	Hour	Min					
1 ID <u>1201</u> Type <u>11</u>	Dispatch <input checked="" type="checkbox"/>	<u>3</u>	<u>20</u>	<u>2021</u>	<u>22:31</u>	<input checked="" type="checkbox"/>	<u>4</u>	<input checked="" type="checkbox"/> Suppression <input type="checkbox"/> EMS <input type="checkbox"/> Other	<input type="checkbox"/>	<input type="checkbox"/>
	Arrival <input checked="" type="checkbox"/>	<u>3</u>	<u>20</u>	<u>2021</u>	<u>22:34</u>	<input checked="" type="checkbox"/>			<input type="checkbox"/>	<input type="checkbox"/>
	Clear <input type="checkbox"/>	<u>3</u>	<u>21</u>	<u>2021</u>	<u>01:44</u>				<input type="checkbox"/>	<input type="checkbox"/>
2 ID <u>1208</u> Type <u>60</u>	Dispatch <input checked="" type="checkbox"/>	<u>3</u>	<u>20</u>	<u>2021</u>	<u>22:31</u>	<input checked="" type="checkbox"/>	<u>1</u>	<input checked="" type="checkbox"/> Suppression <input type="checkbox"/> EMS <input type="checkbox"/> Other	<input type="checkbox"/>	<input type="checkbox"/>
	Arrival <input checked="" type="checkbox"/>	<u>3</u>	<u>20</u>	<u>2021</u>	<u>22:40</u>	<input checked="" type="checkbox"/>			<input type="checkbox"/>	<input type="checkbox"/>
	Clear <input type="checkbox"/>	<u>3</u>	<u>21</u>	<u>2021</u>	<u>01:44</u>				<input type="checkbox"/>	<input type="checkbox"/>
3 ID <u>1210</u> Type <u>92</u>	Dispatch <input checked="" type="checkbox"/>	<u>3</u>	<u>20</u>	<u>2021</u>	<u>22:31</u>	<input checked="" type="checkbox"/>	<u>1</u>	<input checked="" type="checkbox"/> Suppression <input type="checkbox"/> EMS <input type="checkbox"/> Other	<input type="checkbox"/>	<input type="checkbox"/>
	Arrival <input checked="" type="checkbox"/>	<u>3</u>	<u>20</u>	<u>2021</u>	<u>22:34</u>	<input checked="" type="checkbox"/>			<input type="checkbox"/>	<input type="checkbox"/>
	Clear <input type="checkbox"/>	<u>3</u>	<u>21</u>	<u>2021</u>	<u>01:44</u>				<input type="checkbox"/>	<input type="checkbox"/>
4 ID <u> </u> Type <u> </u>	Dispatch <input type="checkbox"/>	<u> </u>	<u> </u>	<u> </u>	<u> </u>	<input type="checkbox"/>	<u> </u>	<input type="checkbox"/> Suppression <input type="checkbox"/> EMS <input type="checkbox"/> Other	<input type="checkbox"/>	<input type="checkbox"/>
	Arrival <input type="checkbox"/>	<u> </u>	<u> </u>	<u> </u>	<u> </u>	<input type="checkbox"/>			<input type="checkbox"/>	<input type="checkbox"/>
	Clear <input type="checkbox"/>	<u> </u>	<u> </u>	<u> </u>	<u> </u>				<input type="checkbox"/>	<input type="checkbox"/>
5 ID <u> </u> Type <u> </u>	Dispatch <input type="checkbox"/>	<u> </u>	<u> </u>	<u> </u>	<u> </u>	<input type="checkbox"/>	<u> </u>	<input type="checkbox"/> Suppression <input type="checkbox"/> EMS <input type="checkbox"/> Other	<input type="checkbox"/>	<input type="checkbox"/>
	Arrival <input type="checkbox"/>	<u> </u>	<u> </u>	<u> </u>	<u> </u>	<input type="checkbox"/>			<input type="checkbox"/>	<input type="checkbox"/>
	Clear <input type="checkbox"/>	<u> </u>	<u> </u>	<u> </u>	<u> </u>				<input type="checkbox"/>	<input type="checkbox"/>
6 ID <u> </u> Type <u> </u>	Dispatch <input type="checkbox"/>	<u> </u>	<u> </u>	<u> </u>	<u> </u>	<input type="checkbox"/>	<u> </u>	<input type="checkbox"/> Suppression <input type="checkbox"/> EMS <input type="checkbox"/> Other	<input type="checkbox"/>	<input type="checkbox"/>
	Arrival <input type="checkbox"/>	<u> </u>	<u> </u>	<u> </u>	<u> </u>	<input type="checkbox"/>			<input type="checkbox"/>	<input type="checkbox"/>
	Clear <input type="checkbox"/>	<u> </u>	<u> </u>	<u> </u>	<u> </u>				<input type="checkbox"/>	<input type="checkbox"/>
7 ID <u> </u> Type <u> </u>	Dispatch <input type="checkbox"/>	<u> </u>	<u> </u>	<u> </u>	<u> </u>	<input type="checkbox"/>	<u> </u>	<input type="checkbox"/> Suppression <input type="checkbox"/> EMS <input type="checkbox"/> Other	<input type="checkbox"/>	<input type="checkbox"/>
	Arrival <input type="checkbox"/>	<u> </u>	<u> </u>	<u> </u>	<u> </u>	<input type="checkbox"/>			<input type="checkbox"/>	<input type="checkbox"/>
	Clear <input type="checkbox"/>	<u> </u>	<u> </u>	<u> </u>	<u> </u>				<input type="checkbox"/>	<input type="checkbox"/>
8 ID <u> </u> Type <u> </u>	Dispatch <input type="checkbox"/>	<u> </u>	<u> </u>	<u> </u>	<u> </u>	<input type="checkbox"/>	<u> </u>	<input type="checkbox"/> Suppression <input type="checkbox"/> EMS <input type="checkbox"/> Other	<input type="checkbox"/>	<input type="checkbox"/>
	Arrival <input type="checkbox"/>	<u> </u>	<u> </u>	<u> </u>	<u> </u>	<input type="checkbox"/>			<input type="checkbox"/>	<input type="checkbox"/>
	Clear <input type="checkbox"/>	<u> </u>	<u> </u>	<u> </u>	<u> </u>				<input type="checkbox"/>	<input type="checkbox"/>
9 ID <u> </u> Type <u> </u>	Dispatch <input type="checkbox"/>	<u> </u>	<u> </u>	<u> </u>	<u> </u>	<input type="checkbox"/>	<u> </u>	<input type="checkbox"/> Suppression <input type="checkbox"/> EMS <input type="checkbox"/> Other	<input type="checkbox"/>	<input type="checkbox"/>
	Arrival <input type="checkbox"/>	<u> </u>	<u> </u>	<u> </u>	<u> </u>	<input type="checkbox"/>			<input type="checkbox"/>	<input type="checkbox"/>
	Clear <input type="checkbox"/>	<u> </u>	<u> </u>	<u> </u>	<u> </u>				<input type="checkbox"/>	<input type="checkbox"/>

Type of Apparatus or Resources

- | | | | |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <p>Ground Fire Suppression</p> <ul style="list-style-type: none"> 11 Engine 12 Truck or aerial 13 Quint 14 Tanker & pumper combination 16 Brush truck 17 ARF (Aircraft Rescue and Firefighting) 10 Ground fire suppression, other <p>Heavy Ground Equipment</p> <ul style="list-style-type: none"> 21 Dozer or plow 22 Tractor 24 Tanker or tender 20 Heavy equipment, other <p>Aircraft</p> <ul style="list-style-type: none"> 41 Aircraft: fixed wing tanker 42 Helitanker 43 Helicopter 40 Aircraft, other | <p>Marine Equipment</p> <ul style="list-style-type: none"> 51 Fire boat with pump 52 Boat, no pump 50 Marine apparatus, other <p>Support Equipment</p> <ul style="list-style-type: none"> 61 Breathing apparatus support 62 Light and air unit 60 Support apparatus, other <p>Medical & Rescue</p> <ul style="list-style-type: none"> 71 Rescue unit 72 Urban Search & rescue unit 73 High angle rescue unit 75 HLS unit 76 ALS unit 70 Medical and rescue unit, other | <p>More Apparatus?
Use Additional
Sheets</p> | <p>Other</p> <ul style="list-style-type: none"> 91 Mobile command post 92 Chief officer car 93 Hazmat unit 94 Type 1 hand crew 95 Type 2 hand crew 99 Privately owned vehicle 00 Other apparatus/resource RM None UU Undetermined |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|

A		FDID	State	MM	DD	YYYY	Station	Incident Number	Exposure	Delete	Change	MFIRS - 10 Personnel					
		CS852	IL	3	20	2021	18T	21-0000243	000	<input type="checkbox"/>	<input type="checkbox"/>						
B Apparatus or Resource		Date and Times					Sent	Number of People	Use	Actions Taken							
Use codes listed below		Check if same as alarm date					<input checked="" type="checkbox"/>		Check ONE box for each apparatus to indicate its main use at the incident.	List up to 4 actions for each apparatus and each personnel.							
		Month	Day	Year	Hours/mins												
1	ID 1201	Dispatch	<input checked="" type="checkbox"/>	3	20	2021	22:31	Sent	<input checked="" type="checkbox"/>	4	<input checked="" type="checkbox"/> Suppression	<input type="checkbox"/> EMS	<input type="checkbox"/> Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	Type 11	Arrival	<input checked="" type="checkbox"/>	3	20	2021	22:34	<input checked="" type="checkbox"/>									
		Clear	<input type="checkbox"/>	3	21	2021	01:44										
Personnel ID	Name	Rank or Grade	Attend	Action Taken	Action Taken	Action Taken	Action Taken										
15309	Anderson, Jacob	CP	<input checked="" type="checkbox"/>														
15321	Czech, Douglas	FF	<input checked="" type="checkbox"/>														
15325	Farias, Miguel	FF	<input checked="" type="checkbox"/>														
15387	Focht, Garrett	FF	<input checked="" type="checkbox"/>														
2	ID 1208	Dispatch	<input checked="" type="checkbox"/>	3	20	2021	22:31	Sent	<input checked="" type="checkbox"/>	1	<input checked="" type="checkbox"/> Suppression	<input type="checkbox"/> EMS	<input type="checkbox"/> Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	Type 60	Arrival	<input checked="" type="checkbox"/>	3	20	2021	22:40	<input checked="" type="checkbox"/>									
		Clear	<input type="checkbox"/>	3	21	2021	01:44										
Personnel ID	Name	Rank or Grade	Attend	Action Taken	Action Taken	Action Taken	Action Taken										
15302	Babinec, John	DC	<input checked="" type="checkbox"/>														
3	ID 1210	Dispatch	<input checked="" type="checkbox"/>	3	20	2021	22:31	Sent	<input checked="" type="checkbox"/>	1	<input checked="" type="checkbox"/> Suppression	<input type="checkbox"/> EMS	<input type="checkbox"/> Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
	Type 92	Arrival	<input checked="" type="checkbox"/>	3	20	2021	22:34	<input checked="" type="checkbox"/>									
		Clear	<input type="checkbox"/>	3	21	2021	01:44										
Personnel ID	Name	Rank or Grade	Attend	Action Taken	Action Taken	Action Taken	Action Taken										
15314	Boyajian, Jeff	FC	<input checked="" type="checkbox"/>														

CS852
FDID

IL
State

3 20
Incident Date

2021

1ST
Station

21-0000243
Incident Number

000
Exposure

Responding
Units/Personnel

Unit	Notify Time	Enroute Time	Arrival Time	Cleared Time
1201 HME 2007 Pumper	22:31:00	22:31:00	22:34:00	01:44:00

Staff ID\Staff Name	Activity	Rank	Position	Role
15309 Anderson, Jacob P	Fire call	Captain	Officer's se	Captain
15321 Czech, Douglas P	Fire call	Firefighter	Driver	Driver of th
15325 Farias, Miguel	Fire call	Firefighter	Rear seat #1	
15387 Focht, Garrett	Fire call	Firefighter	Rear seat #2	

1208 Apparatus/Staff, Utility car	22:31:00	22:36:00	22:40:00	01:44:00
-----------------------------------	----------	----------	----------	----------

Staff ID\Staff Name	Activity	Rank	Position	Role
15302 Babinec, John C	Fire call	Deputy Chie	Driver	Deputy Chief

1210 Fire Chief	22:31:00	22:31:00	22:34:00	01:44:00
-----------------	----------	----------	----------	----------

Staff ID\Staff Name	Activity	Rank	Position	Role
15314 Boyajian, Jeff G	Fire call	Fire Chief	Command	Chief

C8852 FDID *	IL State *	MM DD YYYY 3 20 2021 Incident Date *	1ST Station	21-0000243 Incident Number *	000 Exposure *	Responding Personnel
-----------------	---------------	--------------------------------------------	----------------	---------------------------------	-------------------	-------------------------

Staff ID\Staff Name	Unit	Activity	Position	Rank	PayScl	Hrs	HrsPd	Pts
15309 Anderson, Jacob P	1201	FIRECALL Fire call	OF	CP		3.22	3.22	0.00
15321 Czech, Douglas P	1201	X FIRECALL Fire call	DR	FF		3.22	3.22	0.00
15325 Farias, Miguel	1201	FIRECALL Fire call	R1	FF		3.22	3.22	0.00
15387 Focht, Garrett	1201	FIRECALL Fire call	R2	FF		3.22	3.22	0.00
15302 Babinec, John C	1208	X FIRECALL Fire call	DR	DC		3.22	3.22	0.00
15314 Boyajian, Jeff G	1210	X FIRECALL Fire call	CM	FC		3.22	3.22	0.00

Total Participants: 6

Total Personnel Hours: 19.32

An 'X' next to the unit denotes driver.



ATTACHMENT 4

Hudson Boiler & Tank Company

BOILER REPAIRS --- STACKS --- TANKS

STEEL FABRICATORS AND ERECTORS

3101 SOUTH STATE STREET LOCKPORT, IL 60441

PHONE: (312) 666-4780 FAX (312) 666-5145

www.hudsonboiler.com

July 29, 2020

Koppers, Inc.
3900 S. Laramie Ave.
Cicero, IL 60804

Ref: Jobs #28365 – Repairs to Tar Column V-101 (NB #1039)

Attn: Mr. Dutczak,

Enclosed you will find one (1) copy of the National Board "Form R-1 Report of Repair" for the work we recently performed for the above referenced jobs.

These reports should be retained for future reference. They may be needed from time to time for inspection and insurance purposes.

Thank you for the opportunity to be of service.



Chris Woodill
Hudson Boiler & Tank Co.

cc:

Hudson Boiler and Tank Company - File

FORM R-1 REPORT OF REPAIR
in accordance with provisions of the *National Board Inspection Code*

OW
(Authorized Rep. Initials)
W
(Inspectors Initials)
N/A
(Form "R" Registration no.)
28365
(P.O. no., job no., etc.)

1. WORK PERFORMED BY: Hudson Boiler and Tank Company
(name of repair organization)
3101 S. State St. Lockport, IL 60441
(address)

2. OWNER: Koppers, Inc.
(name)
3900 S. Laramie Ave. Cicero, IL 60804
(address)

3. LOCATION OF INSTALLATION: Koppers, Inc
(name)
3900 S. Laramie Ave. Cicero, IL 60804
(address)

4. ITEM IDENTIFICATION: Pressure Vessel NAME OF ORIGINAL MANUFACTURER: Dixie Steel & Supply Co., Inc.
(boiler, pressure vessel, or piping)

5. IDENTIFYING NOS: 74-413A 1039 V-101 1975
(mfg. serial no.) (National Board no.) (jurisdiction no.) (other) (year built)

6. NBIC EDITION/ADDENDA: 2019
(edition) (addenda)
Original Code of Construction for Item: ASME Section VIII, Div 1 Unk
(name / section / division) (edition / addenda)
Construction Code Used for Repair Performed: ASME Section VIII, Div 1 2019
(name / section / division) (edition / addenda)

7. REPAIR TYPE: welded graphite pressure equipment FRP pressure equipment DOT

8. DESCRIPTION OF WORK: Form R-4, Report Supplementary Sheet is attached FFSA Form (NB-403) is attached
(use Form R-4, if necessary)

Removed 16" x 24" section of 1/2" SA-240-316L shell, approx. 50" from inner head seam, and replaced with new 1/2" SA-240-316L patch plate, rolled to 72" ID. Shearwave UT performed as NDE. Welded (2) 5/16" 316L studs on exterior of SA-240-316L patch plate approx. 8" from lower edge and 4" from left edge. Welded 18" x 35" x 1/2" x 72" OD SA-240-316L wear plate lapped on the interior of the 1/2" SA-240-316L shell patch.
Removed existing 3" nozzle and lap joint flange ("feed nozzle") from shell and replaced by welding new 3" Sch80 SA-312-316L nozzle x 10" to 72" ID" SA-240-316L and a 3" 150# SA-182-316L RFSO flange welded to new 3" Sch80 SA-312-316L nozzle.

N/A Pressure Test, if applied _____ psi MAWP 25/FV _____ psi
(Liquid, Pneumatic, Vacuum, Leak)

9. REPLACEMENT PARTS: (Attached are Manufacturer's Partial Data Reports or Form R-3's properly completed for the following items of this report):
(name of part, item number, data report type or Certificate of Compliance, mfg's name and identifying stamp)
N/A

10. REMARKS:
Welded per HWP-SS-S-1 by #143 B. Gorz, #144 D. Crossen, #146 M. McLaughlin, & #152 T. Buffington. Shearwave UT performed in lieu of RT as NDE on shell patch. PT performed as NDE in lieu of hydrotest.

N/A
(Form "R" Registration no.)
28365
(P.O. no., job no., etc.)

CERTIFICATE OF COMPLIANCE

I, Chris Woodill, certify that to the best of my knowledge and belief the statements made in this report are correct and that all material, construction, and workmanship on this Repair conforms to the *National Board Inspection Code*. National Board "R" Certificate of Authorization No. R-189 Expiration date: 05/29/2022

Repair Organization: Hudson Boiler and Tank Company

Signed: 
(authorized representative)

Date: 07/29/2020

CERTIFICATE OF INSPECTION

I, Zachary Taylor, holding a valid commission issued by the National Board of Boiler and Pressure Vessel Inspectors and certificate of competency, where required, issued by the Jurisdiction of Illinois and employed by The Hartford Steam Boiler Inspection and Insurance Company of Hartford, CT have inspected the work described in this report on July 29, 2020 and state that to the best of my knowledge and belief, this work complies with the applicable requirements of the *National Board Inspection Code*. By signing this certificate, neither the undersigned nor my employer makes any warranty, expressed or implied, concerning the work described in this report. Furthermore, neither the undersigned nor my employer shall be liable in any manner for any personal injury, property damage, or loss of any kind arising from or connected with this inspection.

Commissions: 16506R IL02386IC
(National Board and Jurisdiction no. including endorsement)

Signed: 
(inspector)

Date: 07/29/2020



**Boiler Inspection
Services Company**

Engineering, Inspection & Testing

1755 S. Naperville Rd.
Suite #100
Wheaton, IL 60189
Tel: (630) 510-3223
Fax: (630) 510-3261
www.boilerinspection.com

INSPECTION, TESTING, AND ASSESSMENT

NO. 2 REBOILER

FOR

KOPPERS, INC.

CICERO, ILLINOIS

SUBMITTED BY:

BOILER INSPECTION SERVICES COMPANY

**1755 S. Naperville Rd., Suite 100
Wheaton, IL 60189**

Dated: November 2020

***** THE BOILER & PRESSURE VESSELS EVALUATION SPECIALISTS *****

TABLE OF CONTENTS

INTRODUCTION	1
OBJECT DESCRIPTION	2
SUMMARY	3
RECOMMENDATIONS	6
CALCULATIONS AND ASSESSMENT	7

APPENDICES

ULTRASONIC THICKNESS TESTING RESULTS
DESIGN DRAWING
PHOTOGRAPHIC DOCUMENTATION

INTRODUCTION

On November 13, 2020, Boiler Inspection Services Company performed inspection, testing, and assessment of No. 2 Reboiler for Koppers, Inc. located in Cicero, Illinois. The objective of the assessment is to determine the existing condition of No. 2 Reboiler.

The reboilers' physical condition, description and evaluation are based upon information obtained through visual inspection, nondestructive testing by means of ultrasonic thickness (UT) testing and assessment of present operation, maintenance, and repair data. The ultrasonic thickness (UT) testing was performed on selected accessible surfaces of the No. 2 Reboiler coils.

An exit meeting was held on November 13, 2020 with Mr. Michael Dutczak, Reliability Engineer, to relate the preliminary results of the evaluation.

This evaluation was directed by Ron Avalos Project Manager and NDE Level III, and assisted by Casimir Soczyk, NDE Level II.

We thank Koppers, Inc. personnel for the courtesies extended to us during our on-site inspection.

If you have any questions regarding this report or the services offered by Boiler Inspection Services Company, please contact the Operations Manager at (630) 510-3223.

OBJECT DESCRIPTION

OBJECT	-	No. 2 Reboiler
Manufacturer	-	The American Schack Company, Inc.
National Board #	-	Unknown
Max Design Pressure	-	120 psi @ 650°F
Year Built	-	1967 (Estimated)
Coil Size	-	2 ½" OD (Assumed)
Material	-	SA-106-B Seamless (Assumed)

SUMMARY

INTERNAL INSPECTION

Visual internal inspection of the reboiler revealed the following:

- A) The coil was replaced in January 2020. No indications of significant corrosion or erosion were noted on the coil. Repair window welds were observed on tube 36 and 38. The accessible circumferential coil welds appeared to be in satisfactory condition. (See photos)
- B) The broken U-bolts noted in the 2017 inspection were replaced during the coil replacement. No broken U-bolts were observed. (See photos)
- C) Light staining and moderate black discoloration (soot) were noted on the coil throughout the reboiler. The presence of soot is an indication of flame impingement and/or low firing of the burner. (See photos)
- D) As in the 2017 inspection, the manway opening showed light to moderate corrosion and pitting; however, a crack and warping in the metal ring were also observed. (See photos)
- E) The significant chunk of refractory and insulation missing at the top of the reboiler noted in the 2017 inspection has been repaired; however, light cracking and spalling were observed in the refractory. Areas of water staining were noted on the refractory around the coil supports attached to the top head, indications of possible leakage into the reboiler. (See photos)
- F) Areas of eroded or scrapped away refractory were observed on the accessible shell refractory. The accessible shell refractory appeared to be in satisfactory condition. Openings were noted in the reboiler at the coil inlet and outlet. Light accumulation of debris was observed at the bottom. (See photos)
- G) The burner and burner box appeared to be in satisfactory condition for continued service; however, accumulation of loose insulation and debris were observed. (See photos)

- H) Light general corrosion was observed on the economizer tubes at the top of the reboiler. Several bent fins were noted; however, it is not considered significant. (See photos)

EXTERNAL INSPECTION

Visual external inspection of the reboiler revealed the following:

- A) A crack in the southeast side of the burner box underneath the nozzle was observed. (See photos)
- B) Light general corrosion was observed on the bottom plate of the reboiler, as noted in the 2017 inspection. Areas of general corrosion were also observed at the top of the reboiler. (See photos)
- C) A small patch of moderate general corrosion was observed on the shell of the reboiler. This condition was noted during the 2017 inspection and does not appear to be significantly worse. (See photos)
- D) The inspection port was burnt and deteriorated. Cracks were noted around the bolts. These conditions were noted during the 2017 inspection. (See photos)
- E) Staining and moderate general corrosion at the top of the vessel were still observed. (See photos)
- F) Light cracks were noted in the concrete pillars of the support legs of the reboiler and is not considered significant at this time. This condition was noted during the 2017 inspection. (See photos)
- G) Significant cracks and separation in the ladder support welds connecting the ladder to the support bracket were noted. This condition was noted during the 2017 inspection and does not appear to be significantly worse. (See photos)

NONDESTRUCTIVE TESTING (NDE)

NDE testing performed on the boiler revealed the following:

- A) Ultrasonic thickness (UT) testing of the coil revealed no significant thickness wall loss at the tested locations. (See UT Results)

RECOMMENDATIONS

1. The reboiler's burner should be tuned-up by a qualified and experienced burner repair company prior to the operation of the reboiler to prevent flame impingement and ensure the correct fuel to air ratio for proper combustion and reboiler efficiency. The black soot currently on the coil tubes throughout the reboiler be removed prior to operation to better serve as an indicator for the tuning of the burner.
2. The crack in the southeast side of the burner box underneath the nozzle should be repaired prior to the operation of the reboiler.
3. The cracks and separation observed in the ladder support welds connecting the ladder to the support bracket should be repaired at the next available opportunity.
4. The accumulation of loose debris at the bottom of the reboiler and burner box should be removed prior to the operation of the reboiler.
5. The light cracks and spalling refractory observed on the top head of the reboiler should be repaired at the next available opportunity. The refractory throughout the reboiler should be monitored every annual shutdown and repaired as needed.
6. The corrosion/rust observed on the exterior of the reboiler should be removed/cleaned and repainted with an appropriate paint to prevent further corrosion.

CALCULATIONS AND ASSESSMENT

Reboiler No.	-	2
Year Built	-	1967 (Estimated)
MAWP	-	120 psi @ 650°F

COIL TUBE CALCULATIONS



Tube Size	-	2 ½" OD (Assumed)
Tube Material	-	SA-106-B Seamless (Assumed)
Material Stress Value	-	15,000 psi (Assumed)
Lowest thickness measured	-	.210"
Minimum required thickness @ 120 psi	-	.023"
Remaining Actual Thickness	-	.187"

Note: *The lowest thickness measured is greater than the minimum required thickness. No further calculations are required.*

- **ASME Section VIII – Div, 1 – 1967 Edition.**

ULTRASONIC THICKNESS TESTING RESULTS

KOPPERS, INC.
CICERO, ILLINOIS
REBOILER #2
ULTRASONIC THICKNESS READINGS
COIL TUBES



NOTE: 0° = INLET

COIL LOCATIONS


	0°	45°	90°	135°	180°	225°	270°	315°
50	0.236	0.241	0.238	0.234	0.231	0.236	0.238	0.247
49	0.234	0.238	0.231	0.241	0.222	0.243	0.247	0.241
48	0.231	0.234	0.241	0.245	0.249	0.231	0.241	0.229
47	0.224	0.234	0.241	0.231	0.240	0.238	0.240	0.239
46	0.244	0.231	0.234	0.236	0.247	0.234	0.230	0.229
45	0.238	0.235	0.236	0.233	0.224	0.236	0.238	0.247
44	0.248	0.236	0.234	0.237	0.239	0.241	0.240	0.240
43	0.241	0.234	0.238	0.233	0.234	0.224	0.228	0.229
42	0.241	0.234	0.228	0.224	0.234	0.241	0.248	0.242
41	0.245	0.241	0.243	0.246	0.234	0.235	0.248	0.236
40	0.248	0.236	0.245	0.250	0.231	0.233	0.236	0.243
39	0.231	0.234	0.239	0.241	0.244	0.245	0.246	0.244
38	0.226	0.224	0.234	0.219	0.233	0.234	0.228	0.231
37	0.217	0.226	0.224	0.231	0.233	0.238	0.242	0.236
36	0.227	0.245	0.238	0.244	0.238	0.232	0.232	0.234
35	0.225	0.228	0.224	0.223	0.224	0.226	0.229	0.230
34	0.238	0.241	0.245	0.244	0.241	0.231	0.224	0.228
33	0.235	0.231	0.238	0.228	0.234	0.238	0.227	0.229
32	0.234	0.233	0.231	0.228	0.224	0.247	0.241	0.234
31	0.228	0.227	0.231	0.225	0.226	0.226	0.228	0.224
30	0.238	0.234	0.231	0.234	0.236	0.233	0.241	0.245
29	0.225	0.228	0.231	0.234	0.244	0.245	0.248	0.231
28	0.232	0.227	0.231	0.234	0.233	0.241	0.229	0.228
27	0.228	0.234	0.219	0.233	0.234	0.228	0.232	0.232
26	0.232	0.229	0.224	0.228	0.224	0.226	0.224	0.241
25	0.241	0.249	0.248	0.246	0.222	0.231	0.241	0.234
24	0.231	0.222	0.241	0.251	0.248	0.244	0.246	0.238
23	0.228	0.229	0.222	0.228	0.237	0.231	0.240	0.228
22	0.249	0.244	0.241	0.230	0.236	0.248	0.241	0.245
21	0.234	0.233	0.220	0.237	0.241	0.234	0.234	0.231
20	0.241	0.247	0.233	0.234	0.242	0.239	0.241	0.229
19	0.213	0.234	0.223	0.233	0.245	0.239	0.243	0.228
18	0.238	0.233	0.238	0.241	0.250	0.244	0.246	0.248
17	0.238	0.220	0.224	0.243	0.241	0.234	0.235	0.243
16	0.238	0.243	0.238	0.233	0.239	0.241	0.239	0.234
15	0.236	0.234	0.228	0.241	0.245	0.241	0.229	0.237
14	0.235	0.239	0.234	0.235	0.231	0.229	0.222	0.234
13	0.224	0.224	0.223	0.224	0.224	0.238	0.228	0.229
12	0.228	0.230	0.229	0.230	0.229	0.228	0.226	0.227
11	0.232	0.222	0.232	0.227	0.232	0.232	0.233	0.235
10	0.226	0.226	0.228	0.228	0.227	0.227	0.224	0.233
9	0.227	0.229	0.228	0.229	0.219	0.228	0.227	0.228
8	0.230	0.232	0.232	0.232	0.234	0.231	0.225	0.221
7	0.241	0.241	0.242	0.241	0.241	0.239	0.224	0.228
6	0.231	0.233	0.210	0.227	0.226	0.234	0.230	0.233
5	0.240	0.238	0.241	0.233	0.241	0.240	0.241	0.240
4	0.232	0.238	0.234	0.241	0.243	0.238	0.239	0.241
3	0.236	0.241	0.238	0.238	0.235	0.236	0.236	0.234
2	0.229	0.240	0.243	0.222	0.243	0.241	0.239	0.240
1	0.227	0.235	0.231	0.236	0.235	0.236	0.235	0.235

CLIENT:	KOPPERS, INC.	INSPECTION ENGINEER:	
TITLE:	REBOILER #2	DRAWN BY:	M. COLLINS
		CAD SUPER:	D. JIMENEZ
		SCALE:	NONE

BOILER INSPECTION SERVICES COMPANY
1755 S. Naperville Rd. Suite #100
Wheaton, Illinois 60189

DESIGN DRAWING

F-201



Remove cap
before use of
tar heater
to prevent
burning oil
from A-A

Notes:
1. DESIGN, M. J. SCHACK, JR. CO., PITTSBURGH, PENNSYLVANIA
BY JOHN J. SCHACK, JR., DESIGNER, PITTSBURGH, PENNSYLVANIA
CHECKED BY M. J. SCHACK, JR., DESIGNER, PITTSBURGH, PENNSYLVANIA
DATE 10/15/50


Estimated Weight
Tar Heater 500 lbs.
Steel 100 lbs.
Copper 100 lbs.
Misc. 50 lbs.
Total 750 lbs.

CERTIFIED PRINT
DATE 10/15/50
APP-60-197


THE AMERICAN SCHACK COMPANY, INC. PITTSBURGH, PA.	
TAR HEATER	
1	Steel Tank
2	Copper Coil
3	Miscellaneous
4	Anchor Bolt
5	Washer
6	Nut
7	Lock Washer
8	Cap Screw
9	Flange
10	Bracket
11	Support
12	Bracket
13	Support
14	Bracket
15	Support
16	Bracket
17	Support
18	Bracket
19	Support
20	Bracket
21	Support
22	Bracket
23	Support
24	Bracket
25	Support
26	Bracket
27	Support
28	Bracket
29	Support
30	Bracket
31	Support
32	Bracket
33	Support
34	Bracket
35	Support
36	Bracket
37	Support
38	Bracket
39	Support
40	Bracket
41	Support
42	Bracket
43	Support
44	Bracket
45	Support
46	Bracket
47	Support
48	Bracket
49	Support
50	Bracket
51	Support
52	Bracket
53	Support
54	Bracket
55	Support
56	Bracket
57	Support
58	Bracket
59	Support
60	Bracket
61	Support
62	Bracket
63	Support
64	Bracket
65	Support
66	Bracket
67	Support
68	Bracket
69	Support
70	Bracket
71	Support
72	Bracket
73	Support
74	Bracket
75	Support
76	Bracket
77	Support
78	Bracket
79	Support
80	Bracket
81	Support
82	Bracket
83	Support
84	Bracket
85	Support
86	Bracket
87	Support
88	Bracket
89	Support
90	Bracket
91	Support
92	Bracket
93	Support
94	Bracket
95	Support
96	Bracket
97	Support
98	Bracket
99	Support
100	Bracket



TOP VIEW



SECTION A-A



SECTION B-B



ANCHOR BOLT PLAN

1" in Anchor Bolt Use 5/8" Dia. Bolt
2" in 1/2" Dia. Washer 3/4" Dia. Nut
3/4" Dia. Lock Washer 3/4" Dia. Nut

2" in 1/2" Dia. Washer 3/4" Dia. Nut
3/4" Dia. Lock Washer 3/4" Dia. Nut
3/4" Dia. Nut 3/4" Dia. Washer

PHOTOGRAPHIC DOCUMENTATION

INTERNAL

The following ten (10) photos show the internal condition of the reboiler. A crack and warping in the manway metal ring were observed. Areas of water staining were observed in the refractory around top head attachments. Areas of eroded or scrapped away shell refractory was noted. Light cracking and spalling were noted in the top refractory. Openings were observed in the reboiler at the coil inlet and outlet. Light general corrosion and bent fins were noted on the accessible economizer tubes.

1)



2)



The following ten (10) photos show the internal condition of the reboiler. A crack and warping in the manway metal ring were observed. Areas of water staining were observed in the refractory around top head attachments. Areas of eroded or scrapped away shell refractory was noted. Light cracking and spalling were noted in the top refractory. Openings were observed in the reboiler at the coil inlet and outlet. Light general corrosion and bent fins were noted on the accessible economizer tubes.

3)



4)



The following ten (10) photos show the internal condition of the reboiler. A crack and warping in the manway metal ring were observed. Areas of water staining were observed in the refractory around top head attachments. Areas of eroded or scrapped away shell refractory was noted. Light cracking and spalling were noted in the top refractory. Openings were observed in the reboiler at the coil inlet and outlet. Light general corrosion and bent fins were noted on the accessible economizer tubes.

5)



6)



The following ten (10) photos show the internal condition of the reboiler. A crack and warping in the manway metal ring were observed. Areas of water staining were observed in the refractory around top head attachments. Areas of eroded or scrapped away shell refractory was noted. Light cracking and spalling were noted in the top refractory. Openings were observed in the reboiler at the coil inlet and outlet. Light general corrosion and bent fins were noted on the accessible economizer tubes.

7)



8)



The following ten (10) photos show the internal condition of the reboiler. A crack and warping in the manway metal ring were observed. Areas of water staining were observed in the refractory around top head attachments. Areas of eroded or scrapped away shell refractory was noted. Light cracking and spalling were noted in the top refractory. Openings were observed in the reboiler at the coil inlet and outlet. Light general corrosion and bent fins were noted on the accessible economizer tubes.

9)




10)



The following ten (10) photos show the condition of the coil tubes and U-bolts. No indications of significant corrosion or erosion were noted on the coil. Repair window welds were observed on tubes 36 and 38. Light staining and moderate black discoloration (soot) were noted on the coil throughout. No broken U-bolts were observed.

1)



2)



The following ten (10) photos show the condition of the coil tubes and U-bolts. No indications of significant corrosion or erosion were noted on the coil. Repair window welds were observed on tubes 36 and 38. Light staining and moderate black discoloration (soot) were noted on the coil throughout. No broken U-bolts were observed.

3)



4)




The following ten (10) photos show the condition of the coil tubes and U-bolts. No indications of significant corrosion or erosion were noted on the coil. Repair window welds were observed on tubes 36 and 38. Light staining and moderate black discoloration (soot) were noted on the coil throughout. No broken U-bolts were observed.

5)



6)



The following ten (10) photos show the condition of the coil tubes and U-bolts. No indications of significant corrosion or erosion were noted on the coil. Repair window welds were observed on tubes 36 and 38. Light staining and moderate black discoloration (soot) were noted on the coil throughout. No broken U-bolts were observed.

7)



8)



The following ten (10) photos show the condition of the coil tubes and U-bolts. No indications of significant corrosion or erosion were noted on the coil. Repair window welds were observed on tubes 36 and 38. Light staining and moderate black discoloration (soot) were noted on the coil throughout. No broken U-bolts were observed.

9)



10)



The following four (4) photos show the internal condition of the burner and burner box. The burner and burner box appeared to be in satisfactory condition for continued service; however, accumulation of loose insulation and debris were observed.

1)



2)



The following four (4) photos show the internal condition of the burner and burner box. The burner and burner box appeared to be in satisfactory condition for continued service; however, accumulation of loose insulation and debris were observed.

3)



4)



EXTERNAL

The following sixteen (16) photos show the external condition of the reboiler. Areas of general corrosion were observed on the exterior of the reboiler. A crack in the southeast side of the burner box was observed. Cracks were noted around the bolts of the inspection ports. Light cracks were noted in the concrete pillars of the support legs. Significant cracks and separation in the ladder support welds were noted.

1)



2)



The following sixteen (16) photos show the external condition of the reboiler. Areas of general corrosion were observed on the exterior of the reboiler. A crack in the southeast side of the burner box was observed. Cracks were noted around the bolts of the inspection ports. Light cracks were noted in the concrete pillars of the support legs. Significant cracks and separation in the ladder support welds were noted.

3)



4)




The following sixteen (16) photos show the external condition of the reboiler. Areas of general corrosion were observed on the exterior of the reboiler. A crack in the southeast side of the burner box was observed. Cracks were noted around the bolts of the inspection ports. Light cracks were noted in the concrete pillars of the support legs. Significant cracks and separation in the ladder support welds were noted.

5)



6)



The following sixteen (16) photos show the external condition of the reboiler. Areas of general corrosion were observed on the exterior of the reboiler. A crack in the southeast side of the burner box was observed. Cracks were noted around the bolts of the inspection ports. Light cracks were noted in the concrete pillars of the support legs. Significant cracks and separation in the ladder support welds were noted.

7)



8)



The following sixteen (16) photos show the external condition of the reboiler. Areas of general corrosion were observed on the exterior of the reboiler. A crack in the southeast side of the burner box was observed. Cracks were noted around the bolts of the inspection ports. Light cracks were noted in the concrete pillars of the support legs. Significant cracks and separation in the ladder support welds were noted.

9)



10)



The following sixteen (16) photos show the external condition of the reboiler. Areas of general corrosion were observed on the exterior of the reboiler. A crack in the southeast side of the burner box was observed. Cracks were noted around the bolts of the inspection ports. Light cracks were noted in the concrete pillars of the support legs. Significant cracks and separation in the ladder support welds were noted.

11)



12)



The following sixteen (16) photos show the external condition of the reboiler. Areas of general corrosion were observed on the exterior of the reboiler. A crack in the southeast side of the burner box was observed. Cracks were noted around the bolts of the inspection ports. Light cracks were noted in the concrete pillars of the support legs. Significant cracks and separation in the ladder support welds were noted.

13)



14)



The following sixteen (16) photos show the external condition of the reboiler. Areas of general corrosion were observed on the exterior of the reboiler. A crack in the southeast side of the burner box was observed. Cracks were noted around the bolts of the inspection ports. Light cracks were noted in the concrete pillars of the support legs. Significant cracks and separation in the ladder support welds were noted.

15)



16)





SPECIALTY PLANT SERVICES

12221 East Sam Houston Parkway North • Houston, TX 77044 • Phone 1-713-427-7700 • Fax 1-713-427-7747

Fixed Equipment Internal Inspection Report

Unit:	<u>U-03</u>	Insp. Date:	<u>11-10-2020 THRU 11-XX-2020</u>	
Equipment:	<u>V-101 & V-201</u>			
Description:	<u>TAR FRACTIONATOR</u>		Inspector(s):	<u>STEPHEN ZANELLA</u> API 510#: <u>68344</u>
Serial Number:	<u>74-413B</u>	National Board:	<u>N/A</u>	API 510#: _____
Customer:	<u>KOPPERS</u>		Location:	<u>U-03 TAR PLANT</u>
Street Address:	<u>3900 S LARAMIE AVE</u>		Contact:	<u>KYLE URBAN</u>
City:	<u>CICERO</u>	State:	<u>ILLINOIS</u>	Outage: <u>NO</u>
		Zip Code:	<u>60804</u>	

SUMMARY:

REPAIR SUMMARY:

RECOMMENDATIONS:

Condition Before Cleaning:

Cleaning Method:

Accessibility:

SHELL & HEADS:

Top Head:

Shell:

Bottom Head:

Internal Components:

Nozzles:





Disclaimer: The statements, findings, results, and recommendations contained within this report are based upon the site conditions, as they existed at the time of inspection and are limited to the information and findings of the vessel condition. Any non-destructive testing and visual observations made were representative of the pressure vessel conditions at the time of inspection. It is understood by the parties that the pressure vessel condition could change with time. This report was prepared for the exclusive use and benefit of the customer. Any inspection and testing were performed using the standard of care and level of skill ordinarily exercised under similar circumstances by individuals performing similar tasks in the same geographic region. No representation, guaranty or warranty expressed or implied is made as to the statements, findings, results, or recommendations included in this report.

Fixed Equipment Internal Inspection Report

Unit: U-03
Equipment: V-101 & V-201
Description: TAR FRACTIONATOR
Serial Number: 74-413B National Board: N/A

Insp. Date: 11-10-2020 THRU 11-XX-2020
Inspector(s): STEPHEN ZANELLA API 510#: 68344
API 510#: _____

Internal Pictures:







Disclaimer: The statements, findings, results, and recommendations contained within this report are based upon the site conditions, as they existed at the time of inspection and are limited to the information and findings of the vessel condition. Any non-destructive testing and visual observations made were representative of the pressure vessel conditions at the time of inspection. It is understood by the parties that the pressure vessel condition could change with time. This report was prepared for the exclusive use and benefit of the customer. Any inspection and testing were performed using the standard of care and level of skill ordinarily exercised under similar circumstances by individuals performing similar tasks in the same geographic region. No representation, guaranty or warranty expressed or implied is made as to the statements, findings, results, or recommendations included in this report.

Fixed Equipment Internal Inspection Report

Unit: U-03
Equipment: V-101 & V-201
Description: TAR FRACTIONATOR
Serial Number: 74-413B National Board: N/A

Insp. Date: 11-10-2020 THRU 11-XX-2020

Inspector(s): STEPHEN ZANELLA API 510#: 68344
API 510#: _____



Disclaimer: The statements, findings, results, and recommendations contained within this report are based upon the site conditions, as they existed at the time of inspection and are limited to the information and findings of the vessel condition. Any non-destructive testing and visual observations made were representative of the pressure vessel conditions at the time of inspection. It is understood by the parties that the pressure vessel condition could change with time. This report was prepared for the exclusive use and benefit of the customer. Any inspection and testing were performed using the standard of care and level of skill ordinarily exercised under similar circumstances by individuals performing similar tasks in the same geographic region. No representation, guaranty or warranty expressed or implied is made as to the statements, findings, results, or recommendations included in this report.

Fixed Equipment Internal Inspection Report

Unit: U-03
Equipment: V-101 & V-201
Description: TAR FRACTIONATOR
Serial Number: 74-413B National Board: N/A

Insp. Date: 11-10-2020 THRU 11-XX-2020
Inspector(s): STEPHEN ZANELLA API 510#: 68344
API 510#: _____

Reference ID: 9



Description: 3x .100" corrosion at N 2 TOC Vapor Outlet shell

Reference ID: 10



Description: Tray ring 20 vertical weld seam has .150 x .200" pin hole and tray ring splice has a crack and pin hole in the attachment weld (unknown depth of crack)

Reference ID: 11



Description: Manway Nozzle 1E mechanical damage and arc strike

Reference ID: 12



Description: Vertical seam near bottom head of dehydrator. Undercut/weld defect .040" deep

Disclaimer: The statements, findings, results, and recommendations contained within this report are based upon the site conditions, as they existed at the time of inspection and are limited to the information and findings of the vessel condition. Any non-destructive testing and visual observations made were representative of the pressure vessel conditions at the time of inspection. It is understood by the parties that the pressure vessel condition could change with time. This report was prepared for the exclusive use and benefit of the customer. Any inspection and testing were performed using the standard of care and level of skill ordinarily exercised under similar circumstances by individuals performing similar tasks in the same geographic region. No representation, guaranty or warranty expressed or implied is made as to the statements, findings, results, or recommendations included in this report.

Fixed Equipment Internal Inspection Report

Unit: U-03
Equipment: V-101 & V-201
Description: TAR FRACTIONATOR
Serial Number: 74-413B National Board: N/A

Insp. Date: 11-10-2020 THRU 11-XX-2020
Inspector(s): STEPHEN ZANELLA API 510#: 68344
API 510#: _____

Reference ID: 13



Description: Baffle bracket attachment weld below tray 21. Typical 4 places. Weld quality issues, arc strikes, undercutting, buckshot, etc.

Reference ID: 14



Description: Baffle bracket attachment weld below tray 21. Typical 4 places. Weld quality issues, arc strikes, undercutting, buckshot, etc.

Reference ID: 15



Description: Baffle bracket attachment weld below tray 21. Crack developing at the top of the weld. Weld quality issues, arc strikes, undercutting, buckshot.

Reference ID: 16



Description: Shell defect areas above tray 21 @ xxx degrees

Disclaimer: The statements, findings, results, and recommendations contained within this report are based upon the site conditions, as they existed at the time of inspection and are limited to the information and findings of the vessel condition. Any non-destructive testing and visual observations made were representative of the pressure vessel conditions at the time of inspection. It is understood by the parties that the pressure vessel condition could change with time. This report was prepared for the exclusive use and benefit of the customer. Any inspection and testing were performed using the standard of care and level of skill ordinarily exercised under similar circumstances by individuals performing similar tasks in the same geographic region. No representation, guaranty or warranty expressed or implied is made as to the statements, findings, results, or recommendations included in this report.

Fixed Equipment Internal Inspection Report

Unit: U-03
Equipment: V-101 & V-201
Description: TAR FRACTIONATOR
Serial Number: 74-413B National Board: N/A

Insp. Date: 11-10-2020 THRU 11-XX-2020
Inspector(s): STEPHEN ZANELLA API 510#: 68344
API 510#: _____

Reference ID: 17



Description: Shell defect areas above tray 22@ xxx degrees. .090 x .325". Arc strikes.

Reference ID: 18



Description: Erosion of weld metal buildup area above tray 22. Unknown depth of erosion.

Reference ID: 19



Description: Vertical seam above tray 22. Undercut/weld defect .030" deep, pin hole.

Reference ID: 20







Description: Thru hole above tray 22 @west side. .375" diameter

Disclaimer: The statements, findings, results, and recommendations contained within this report are based upon the site conditions, as they existed at the time of inspection and are limited to the information and findings of the vessel condition. Any non-destructive testing and visual observations made were representative of the pressure vessel conditions at the time of inspection. It is understood by the parties that the pressure vessel condition could change with time. This report was prepared for the exclusive use and benefit of the customer. Any inspection and testing were performed using the standard of care and level of skill ordinarily exercised under similar circumstances by individuals performing similar tasks in the same geographic region. No representation, guaranty or warranty expressed or implied is made as to the statements, findings, results, or recommendations included in this report.

Fixed Equipment Internal Inspection Report

Unit: U-03
Equipment: V-101 & V-201
Description: TAR FRACTIONATOR
Serial Number: 74-413B National Board: N/A

Insp. Date: 11-10-2020 THRU 11-XX-2020
Inspector(s): STEPHEN ZANELLA API 510#: 68344
API 510#: _____



Disclaimer: The statements, findings, results, and recommendations contained within this report are based upon the site conditions, as they existed at the time of inspection and are limited to the information and findings of the vessel condition. Any non-destructive testing and visual observations made were representative of the pressure vessel conditions at the time of inspection. It is understood by the parties that the pressure vessel condition could change with time. This report was prepared for the exclusive use and benefit of the customer. Any inspection and testing were performed using the standard of care and level of skill ordinarily exercised under similar circumstances by individuals performing similar tasks in the same geographic region. No representation, guaranty or warranty expressed or implied is made as to the statements, findings, results, or recommendations included in this report.

Fixed Equipment Internal Inspection Report

Unit: U-03
Equipment: V-101 & V-201
Description: TAR FRACTIONATOR
Serial Number: 74-413B National Board: N/A

Insp. Date: 11-10-2020 THRU 11-XX-2020

Inspector(s): STEPHEN ZANELLA API 510#: 68344
API 510#: _____

Reference ID: 25



Description: Arc gouged area under tray ring 24. .070 x 1"

Reference ID: 26



Description: Shell defect areas above tray 23 @ xxx degrees

Reference ID: 27



Description: 3 arc gouged areas at tray level 24. Depth as marked

Reference ID: 28







Description: Arc gouged area at tray level 26. .080 x 1.5"

Disclaimer: The statements, findings, results, and recommendations contained within this report are based upon the site conditions, as they existed at the time of inspection and are limited to the information and findings of the vessel condition. Any non-destructive testing and visual observations made were representative of the pressure vessel conditions at the time of inspection. It is understood by the parties that the pressure vessel condition could change with time. This report was prepared for the exclusive use and benefit of the customer. Any inspection and testing were performed using the standard of care and level of skill ordinarily exercised under similar circumstances by individuals performing similar tasks in the same geographic region. No representation, guaranty or warranty expressed or implied is made as to the statements, findings, results, or recommendations included in this report.

Fixed Equipment Internal Inspection Report

Unit: U-03
Equipment: V-101 & V-201
Description: TAR FRACTIONATOR
Serial Number: 74-413B National Board: N/A

Insp. Date: 11-10-2020 THRU 11-XX-2020
Inspector(s): STEPHEN ZANELLA API 510#: 68344
API 510#: _____




Disclaimer: The statements, findings, results, and recommendations contained within this report are based upon the site conditions, as they existed at the time of inspection and are limited to the information and findings of the vessel condition. Any non-destructive testing and visual observations made were representative of the pressure vessel conditions at the time of inspection. It is understood by the parties that the pressure vessel condition could change with time. This report was prepared for the exclusive use and benefit of the customer. Any inspection and testing were performed using the standard of care and level of skill ordinarily exercised under similar circumstances by individuals performing similar tasks in the same geographic region. No representation, guaranty or warranty expressed or implied is made as to the statements, findings, results, or recommendations included in this report.

Fixed Equipment Internal Inspection Report

Unit: U-03
Equipment: V-101 & V-201
Description: TAR FRACTIONATOR
Serial Number: 74-413B National Board: N/A

Insp. Date: 11-10-2020 THRU 11-XX-2020
Inspector(s): STEPHEN ZANELLA API 510#: 68344
API 510#: _____

Reference ID: 33



Description: Undercut area above tray 27. .060 x .500"

Reference ID: 34



Description: Dehyd Vapor nozzle N 4 fillet weld crater crack, arc strikes

Reference ID: 35



Description: Dehyd Vapor nozzle N4 fillet weld crater crack

Reference ID: 36



Description: N28 pin hole with crack and arc strike area. .030" depth of arc strikes

Disclaimer: The statements, findings, results, and recommendations contained within this report are based upon the site conditions, as they existed at the time of inspection and are limited to the information and findings of the vessel condition. Any non-destructive testing and visual observations made were representative of the pressure vessel conditions at the time of inspection. It is understood by the parties that the pressure vessel condition could change with time. This report was prepared for the exclusive use and benefit of the customer. Any inspection and testing were performed using the standard of care and level of skill ordinarily exercised under similar circumstances by individuals performing similar tasks in the same geographic region. No representation, guaranty or warranty expressed or implied is made as to the statements, findings, results, or recommendations included in this report.

Fixed Equipment Internal Inspection Report

Unit: U-03
Equipment: V-101 & V-201
Description: TAR FRACTIONATOR
Serial Number: 74-413B National Board: N/A

Insp. Date: 11-10-2020 THRU 11-XX-2020


Inspector(s): STEPHEN ZANELLA API 510#: 68344
API 510#: _____

Reference ID: 37



Description: close up view of item 36

Reference ID: 38




Description: Indications in top head of dehyd (inside of flash drum). Depths as noted

Reference ID: 39



Description: Close up view of item 38

Reference ID: 40



Description: Indication in wall of flash drum. .190 x 2"

Disclaimer: The statements, findings, results, and recommendations contained within this report are based upon the site conditions, as they existed at the time of inspection and are limited to the information and findings of the vessel condition. Any non-destructive testing and visual observations made were representative of the pressure vessel conditions at the time of inspection. It is understood by the parties that the pressure vessel condition could change with time. This report was prepared for the exclusive use and benefit of the customer. Any inspection and testing were performed using the standard of care and level of skill ordinarily exercised under similar circumstances by individuals performing similar tasks in the same geographic region. No representation, guaranty or warranty expressed or implied is made as to the statements, findings, results, or recommendations included in this report.

